





report date: 2024-03-28

General information

Make	FIAT
Model	500 C POP
Colour	White
Year of manufacture	2011
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-11-20

Pictures 41

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-11-20
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	1

MOT #13	2023-11-21 08:58
MOT test number	173995301222
Result	✓ Passed
Next expiry date	2024-11-20

MOT #12	2022-11-10 15:36
MOT test number	105980556494
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #11	2022-11-10	11:25
MOT test r	number 75018835	4010
Result	× F	ailed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR the ingress	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevers of dirt $(6.1.7 (g) (ii))$	nts
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Offside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))	

MOT #10	2021-11-19 16:53
MOT test number	117307867835
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-11-19 14:27

MOT test number 184705531231

Result X Failed

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt inner boot clip (6.1.7 (g) (ii))

MAJOR Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

DANGEROUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt inner boot clip (6.1.7 (g) (ii))

DANGEROUS Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #8 2021-08-19 06:49

MOT test number 518107236825

Result
✓ Passed

MOT #7 2020-08-24 10:42

MOT test number 737563339842

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2019-02-18 10:10

MOT test number 999606936229

MOT #5 2017-10-06 10:36

MOT test number 446587343549

CarCheck.co.uk page 4/12



report date: 2024-03-28

 MOT #4
 2016-10-13 10:21

 MOT test number
 646732417112

 Result
 ✓ Passed

 MOT #3
 2015-09-22 08:45

 MOT test number
 896166541400

 Result
 ✓ Passed

 Advice
 Exhaust has a minor leak of exhaust gases (7.1.2)

MOT test number

Result

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Pass with rectification (7.3.D.3)

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits

MOT #1

MOT test number

Result

Notice Items removed from driver's view prior to test

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	20 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

_	
Owner	history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0111.5	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-30
Last registration	2023-11-21
Complete history	See info



Registration #1	2011-09-30	11 mi
Registration #2	2014-09-22	14.342 mi
Registration #3	2015-09-22	20.811 mi
Registration #4	2015-09-22	20.811 mi
Registration #5	2016-10-13	24.489 mi
Registration #6	2017-10-06	26.584 mi
Registration #7	2019-02-18	30.068 mi
Registration #8	2020-08-24	34.765 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		D 207 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number0012511