





report date: 2024-03-28

## General information

Make	PEUGEOT
Model	207 SPORTIUM
Colour	White
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/13



## Internet history

## Entry 2

Date 2021-08-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-31

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-07
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	9
Total items failed	6

MOT #14	2023-08-03 10:36
MOT test number	828055714097
Result	✓ Passed
Next expiry date	2024-08-07
Advice Exhaust mounting defective 1 of 2 rear box mounting broken	

MOT #13		2023-08-03 10:36
MOT test number		128543449279
Result		<b>X</b> Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Exhaust mounti	ng defective 1 of 2 rear box mounting broken	
Pass with rectification	Nearside Windscreen washer not working (3.5 (a))	

MOT #12	2022-08-08 09:38
MOT test number	830019388473
Result	<b>✓</b> Passed
Advice Exhaust mounting defective 1 of 2 rear box mounting broken (6.1.2 (a))	

CarCheck.co.uk page 3/13



MOT test number

Result

Pass with rectification

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Exhaust mounting defective 1 of 2 rear box mounting broken (6.1.2 (a))

Pass with rectification

Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

 MOT #10
 2021-08-03 15:38

 MOT test number
 827820018077

 Result
 ✓ Passed

MOT #9 2020-09-24 07:31

MOT test number 674697420603

Result ✓ Passed

MOT #8 2019-09-14 10:47

MOT test number 329661673450

Result ✓ Passed

MOT #7

MOT test number

454280111301

Result

✓ Passed

CarCheck.co.uk page 4/13



MOT test number

Result

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front Outer Brake pad(s) wearing thin very close to 1.5mm (3.5.1g)

Advice

Nearside Front Outer Brake pad(s) wearing thin very close to 1.5mm (3.5.1g)

Advice

Nearside Front Outer Brake pad(s) wearing thin very close to 1.5mm (3.5.1g)

MOT #52016-09-06 14:36MOT test number521966370238Result✓ PassedMOT #42016-09-06 14:36MOT test number814817554188ResultX FailedPass with rectificationFront Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #3

MOT test number

133442086814

Result

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #2

MOT test number

S19052314051

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #1 2014-09-23 15:09

**MOT test number** 377396264229

CarCheck.co.uk page 6/13





# Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OR SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-03-05
Last registration	2023-08-03
Complete history	See info



Registration #1	2012-03-05	21 mi
Registration #2	2014-09-23	11.872 mi
Registration #3	2015-09-05	21.527 mi
Registration #4	2016-09-03	31.941 mi
Registration #5	2016-09-06	32.032 mi
Registration #6	2016-09-06	32.032 mi
Registration #7	2017-10-14	45.187 mi
Registration #8	2018-10-06	56.360 mi
Registration #9	2019-09-14	66.622 mi
Registration #5	2023 03 2 1	
Registration #10	1015 05 11	11.777 es
	100 00 11 100 00 00 100 00 00	11.777 es
Registration #10	100 00 11 100 10 10 100 10 10	11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11		11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11 Registration #12		11.777-00 11.777-00 11.777-00 11.777-00
Registration #10 Registration #11 Registration #12 Registration #13		11 777 46 21 777 46 21 777 46 21 777 46 21 777 46
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		11 177 46 21 177 46 21 177 46 21 177 46 21 177 46 21 177 46

More info >

CarCheck.co.uk page 12/13



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1617 kg

# Additional information

Fuel tank capacity	50 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

**Engine number** FSX46410607