



A008JOV

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS TSI
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg






Internet history

Entry 1

Date	2022-02-08
Pictures	59
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #15	2021-02-23 12:21
MOT test number	926516299553
Result	✓ Passed
Next expiry date	2022-02-27
Advice	Small chips on windscreen
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))
Minor	Front Headlamp lens slightly defective Both (4.1.1 (b) (i))

MOT #14	2021-02-23 09:56
MOT test number	608407268216
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Front Headlamp lens slightly defective Both (4.1.1 (b) (i))
Fail	Front Valve stem seriously damaged Both (5.2.3 (j))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))
Advice	Small chips on windscreen

MOT #13	2020-02-21 12:09
MOT test number	982703089079
Result	✓ Passed
Advice	Offside Front fog light lens cracked

MOT #12	2020-02-20 09:13
MOT test number	608155800696
Result	✗ Failed

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear unable to see spring in cup

Advice Offside Front fog light lens cracked

**MOT #11** 2019-02-28 15:50**MOT test number** 155852095831**Result** ✓ Passed**Advice** Offside Rear wheel binding**Advice** Nearside Front tyre 3+mm**MOT #10** 2019-02-28 08:56**MOT test number** 738469948655**Result** ✗ Failed**Advice** Nearside Front tyre 3+mm**Advice** Offside Rear tyre bald inner**Advice** Offside Rear wheel binding**Fail** Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9** 2018-02-23 12:04**MOT test number** 368222425484**Result** ✓ Passed**Advice** Nearside Rear anti roll bar bush deteraited but not resulting in excessive movement**Advice** Nearside Rear spring carrier arm bush deteraited but not resulting in excessive movement**Advice** Offside Rear anti roll bar bush deteraited but not resulting in excessive movement**Advice** Offside Rear spring carrier arm bush deteraited but not resulting in excessive movement**MOT #8** 2017-02-24 15:26**MOT test number** 211078409118**Result** ✓ Passed

**MOT #7** 2016-02-25 10:52**MOT test number** 326650882255**Result** ✓ Passed**MOT #6** 2015-02-21 10:44**MOT test number** 687392755057**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Unable to access rear inner brake pads for mot purposes**MOT #5** 2014-02-07 14:59**MOT test number** 707998034007**Result** ✓ Passed**Notice** Wipers smearing**Notice** Both rear tyres worn on inner edge**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-03-14 16:34**MOT test number** 127543973450**Result** ✓ Passed**MOT #3** 2012-04-16 10:06**MOT test number** 675417902195**Result** ✓ Passed



MOT #2	2012-04-16 10:06
MOT test number	127557202100
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Pass with rectification	Nearside Front Headlamp aim too low (1.8)

MOT #1	2011-03-02 13:01
MOT test number	479961961099
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-18
Last registration	2021-02-23
Complete history	See info



Registration #1	2008-03-18	21 mi
Registration #2	2011-03-02	27.736 mi
Registration #3	2012-04-16	33.123 mi
Registration #4	2013-03-14	37.365 mi
Registration #5	2014-02-07	52.485 mi
Registration #6	2015-02-21	71.251 mi
Registration #7	2016-02-25	90.758 mi
Registration #8	2017-02-24	107.682 mi
Registration #9	2018-03-02	121.217 mi
Registration #10	2019-03-02	131.217 mi
Registration #11	2020-03-02	141.217 mi
Registration #12	2021-03-02	151.217 mi
Registration #13	2022-03-02	161.217 mi
Registration #14	2023-03-02	171.217 mi
Registration #15	2024-03-02	181.217 mi
Registration #16	2025-03-02	191.217 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

CAX 016127