




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX S (64BHP)
Colour	Grey
Year of manufacture	2007
Top speed	101 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-10
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	35
Total items failed	1

MOT #18	2023-06-22 07:46
MOT test number	431166141362
Result	✓ Passed
Next expiry date	2024-06-21
Minor	Nearside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Advice	Rear rear exhaust silencer corroded

**MOT #17**

2023-06-21 08:11

**MOT test number**

489314335257

**Result****✗ Failed**

- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Rear rear exhaust silencer corroded
- MAJOR** Offside Headlamp aim unable to be tested (4.1.2 (b))
- Minor** Nearside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #16**

2022-07-25 09:45

**MOT test number**

420615457901

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge showing 2.5mm - 185/60 r14 82t (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15**

2021-07-30 10:36

**MOT test number**

563452853669

**Result****✓ Passed**

**MOT #14** 2021-07-30 10:36**MOT test number** 423894162982**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13** 2020-07-27 15:41**MOT test number** 417238199514**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2020-07-21 07:46**MOT test number** 177296466406**Result** ✗ Failed**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**MOT #11** 2019-07-25 08:01**MOT test number** 915886245206**Result** ✓ Passed**MOT #10** 2018-07-24 15:43**MOT test number** 202951406045**Result** ✓ Passed**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9** 2018-07-24 07:59**MOT test number** 173449957180**Result** ✗ Failed**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Rear tyres perished**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front tyre worn/perished**MOT #8** 2017-07-28 08:15**MOT test number** 837714544249**Result** ✓ Passed**Advice** Offside Front Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2016-07-02 08:14**MOT test number** 153259915639**Result** ✓ Passed**Advice** Offside Front Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit 185/60H14 (4.1.E.1)**MOT #6** 2015-07-06 17:14**MOT test number** 987707385165**Result** ✓ Passed



MOT #5	2014-07-15 14:50
MOT test number	706536594195
Result	✓ Passed
MOT #4	2013-07-08 11:56
MOT test number	469619483130
Result	✓ Passed
MOT #3	2012-07-28 12:03
MOT test number	657700012231
Result	✓ Passed
MOT #2	2011-07-25 12:04
MOT test number	906676501224
Result	✓ Passed
MOT #1	2010-07-31 10:02
MOT test number	533162510280
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-07-31
Last registration	2023-06-22
Complete history	<a href="#">See info</a>



Registration #1	2007-07-31	14 mi
Registration #2	2010-07-31	8.078 mi
Registration #3	2011-07-25	9.721 mi
Registration #4	2012-07-28	11.406 mi
Registration #5	2013-07-08	13.572 mi
Registration #6	2014-07-15	16.008 mi
Registration #7	2015-07-06	18.228 mi
Registration #8	2016-07-02	24.292 mi
Registration #9	2017-07-28	34.290 mi
Registration #10	2018-07-24	41.774 mi
Registration #11	2019-06-20	35.000 mi
Registration #12	2020-06-20	35.000 mi
Registration #13	2021-06-20	35.000 mi
Registration #14	2022-06-20	35.000 mi
Registration #15	2023-06-20	35.000 mi
Registration #16	2024-06-20	35.000 mi
Registration #17	2025-06-20	35.000 mi
Registration #18	2026-06-20	35.000 mi
Registration #19	2027-06-20	35.000 mi
Registration #20	2028-06-20	35.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1194 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BME-230048