



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC GRAND EXPRESSION DCI FAP
Colour	Bronze
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	13.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-04-15
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-07
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	16
Total items failed	12

MOT #14	2023-03-16 10:52
MOT test number	547335396036
Result	✓ Passed
Next expiry date	2024-04-07
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2022-04-08 15:57
MOT test number	603112860089
Result	✓ Passed

MOT #12	2021-07-13 19:12
MOT test number	524944516028
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #11 2021-07-08 09:52

MOT test number 252561469664

Result ✗ Failed

Fail Reversing lamp inoperative (4.6.1 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #10 2020-07-18 11:22

MOT test number 546566122179

Result ✓ Passed

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #9 2020-07-17 11:31

MOT test number 337437972975

Result ✗ Failed

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner wall (5.2.3 (d) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively o/s n/s split (3.4 (b) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner wall (5.2.3 (d) (i))

MOT #8 2020-01-18 12:51

MOT test number 784741407147

Result ✓ Passed

MOT #7 2020-01-18 12:51

MOT test number 878896099949

Result ✗ Failed

- Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))



MOT #6	2019-01-17 16:40
MOT test number	540550299111
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5	2018-01-17 16:17
MOT test number	171114181847
Result	✓ Passed
Advice	O/s/r tyre has age related splits
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2017-01-19 16:55
MOT test number	532938833613
Result	✓ Passed

MOT #3	2016-01-20 10:57
MOT test number	767217575812
Result	✓ Passed

MOT #2	2015-08-26 00:00
MOT test number	584801413642
Result	✓ Passed

MOT #1	2014-04-08 12:30
MOT test number	785228594002
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	EFZ3751
Plate since	2024-03-29
Current registration	EFZ3751
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-11-03
Last registration	2023-03-16
Complete history	See info



Registration #1	2010-11-03	21 mi
Registration #2	2014-04-08	6.852 mi
Registration #3	2015-08-26	15.392 mi
Registration #4	2016-01-20	17.922 mi
Registration #5	2017-01-19	27.658 mi
Registration #6	2018-01-17	38.481 mi
Registration #7	2019-01-17	49.433 mi
Registration #8	2020-01-18	57.704 mi
Registration #9	2020-03-20	66.277 mi
Registration #10	2020-05-22	75.152 mi
Registration #11	2020-08-21	84.327 mi
Registration #12	2020-11-20	93.802 mi
Registration #13	2021-03-19	103.577 mi
Registration #14	2021-07-18	113.652 mi
Registration #15	2022-01-17	124.027 mi
Registration #16	2023-03-16	134.702 mi

[More info >](#)



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2077 mm
Height	1645 mm
Length	4560 mm
Wheel base	2770 mm
Kerb weight	1430 kg
Max. allowed weight	2128 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D143105