





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	White
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-27

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date 2021-10-26
Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-15
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	27
Total items failed	3

MOT #14		2023-07-11 14:19
MOT test	number	343035080736
Result		✓ Passed
Next expi	ry date	2024-07-15
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (5.3.4 (a)	Offside Rear Suspension arm pin or bush worn but not resulting in excess(i))	sive movement trailing
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice (5.3.4 (a)	Nearside Rear Suspension arm pin or bush worn but not resulting in exce(i))	essive movement trailing
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2023-07-11 09:21

MOT test number 881497133815

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing (5.3.4 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing (5.3.4 (a) (i))

MOT #12 2022-07-16 13:40

MOT test number 882779644621

Result
✓ Passed

Advice Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))

MOT #11 2021-11-01 15:00

MOT test number 246977580080

Result
✓ Passed

MOT #10 2021-10-31 15:12

MOT test number 681185050099

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm 215/60/16 (5.2.3 (e))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2021-05-26 08:40

MOT test number 286468059200

MOT #8 2020-06-04 10:04

MOT test number 570329631927

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-05-03 14:30

MOT test number 746125475074

Result \(\sqrt{Passed} \)

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush separating (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing

arm bush separating (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2018-05-10 14:27

MOT test number 445203307635

Result

Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5		2017-05-19 14:24
MOT test	number	688484961996
Result		✓ Passed
Advice	Both front tyres worn low on inner edge	
Advice	Small band of pitting on front brake discs	
Advice	Front lower suspension arm front bushes perishing, nearside and offside	
Advice	Both rear tyres starting to perish	
Advice	Both rear trailing arm bushes perishing	

MOT #4	2016 05 21 15:12
MO1 #4	2016-05-31 15:13
MOT test number	937519955443
Result	✓ Passed
MOT #3	2015-06-18 14:41
MOT test number	529079865177
Result	✓ Passed
MOT #2	2014-06-03 12:21
MOT test number	776184754177
Result	✓ Passed
MOT #1	2013-06-10 15:55
MOT test number	145721163176
Result	✓ Passed

CarCheck.co.uk page 6/13



HG10SZD report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	15 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners define the check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.	
manage of the same	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-28
Last registration	2023-07-11
Complete history	See info



Registration #1	2010-06-28	9 mi
Registration #2	2013-06-10	12.202 mi
Registration #3	2014-06-03	14.064 mi
Registration #4	2015-06-18	17.619 mi
Registration #5	2016-05-31	24.593 mi
Registration #6	2017-05-19	28.496 mi
Registration #7	2018-05-10	31.740 mi
Registration #8	2019-05-03	37.304 mi
Registration #9	2020-06-04	43.697 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 ms

More info >

CarCheck.co.uk page 12/13



HG10SZD report date: 2024-03-28

Car features

The FORD factory car options list is only available in the premium report.

S0225 Air conditioning

S0295

S0482

S0501

S0566

S0567

S0569

View the complete FORD factory list for this vehicle <u>here</u>.

More info >

Safety ratings

NCAP rating	444	
-------------	-----	--

Video <u>see crash video</u>



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

AU21080