



MA62VXC

report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO GBT
Colour	Black
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





MOT history

MOT expiry date	2024-10-25
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	28
Total items failed	9

MOT #11	2023-10-13 09:00
MOT test number	886918262668
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2022-10-25 10:03
MOT test number	167294132753
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2021-10-26 17:01
MOT test number	645928909028
Result	✓ Passed

**MOT #8** 2021-02-02 12:54**MOT test number** 141355834088**Result** ✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Integral body structure is deformed and structural rigidity is significantly reduced complete sill severely damaged (6.1.1 (a) (i))
- Advice** Nearside Front wing catching door when opening
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

**MOT #7** 2020-01-31 14:36**MOT test number** 447261519470**Result** ✓ Passed

- Advice** Nearside Front door/wing catching when opened
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front seat mechanism not working
- Advice** Rear exhaust deteriorated
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front outer sill damaged but not weakened

**MOT #6**

2020-01-31 14:36

**MOT test number**

991978555426

**Result****✗ Failed****Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear exhaust deteriorated**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front outer sill damaged but not weakened**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front door/wing catching when opened**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front seat mechanism not working**MOT #5**

2018-11-07 12:25

**MOT test number**

406705001676

**Result****✓ Passed****Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

**MOT #4** 2018-11-01 14:48**MOT test number** 314813893741**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 185/65/15 (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #3** 2017-10-19 13:06**MOT test number** 236881649272**Result** ✓ Passed**MOT #2** 2016-11-04 15:26**MOT test number** 631010176825**Result** ✓ Passed**MOT #1** 2015-10-05 08:52**MOT test number** 465856681627**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
25 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	25 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-25
Last registration	2023-10-13
Complete history	<a href="#">See info</a>



Registration #1	2012-09-25	8 mi
Registration #2	2015-10-05	27.551 mi
Registration #3	2016-11-04	38.159 mi
Registration #4	2017-10-19	40.708 mi
Registration #5	2018-11-01	55.279 mi
Registration #6	2018-11-07	55.332 mi
Registration #7	2019-05-29	55.332 mi
Registration #8	2019-05-29	55.332 mi
Registration #9	2019-05-29	55.332 mi
Registration #10	2019-05-29	55.332 mi
Registration #11	2019-05-29	55.332 mi
Registration #12	2023-10-13	55.332 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number	0091898
---------------	---------