



F673HNN

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CARAVELLE CARAVELLE 78PS
Colour	White
Year of manufacture	1988
Gearbox	-Manual

Engine & fuel consumption

Engine capacity	1.915 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-04
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-14
MOT pass rate	83 %
MOT passed	19
Failed MOT tests	4
Total advice items	67
Total items failed	9

MOT #23	2023-12-22 12:52
MOT test number	290517461214
Result	✓ Passed
Next expiry date	2025-01-14

MOT #22	2023-01-05 11:54
MOT test number	307235322588
Result	✓ Passed
Advice	Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear inner bush (5.3.4 (a) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #21**

2022-01-15 11:10

MOT test number

763498118607

Result

✓ Passed

Advice Suspension component mounting prescribed area is corroded but not considered excessive all mountings (5.3.6 (a) (i))

Advice Offside Suspension component mounting prescribed area damaged but not considered excessive outer sill (5.3.6 (a) (i))

Advice Underside of vehicle is corroded but sound

Advice Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced all mountings (5.3.3 (b) (i))

Advice Nearside Suspension component mounting prescribed area damaged but not considered excessive outer sill (5.3.6 (a) (i))

Advice Suspension arm corroded but not seriously weakened all suspension arms (5.3.3 (b) (i))

MOT #20

2021-01-28 13:02

MOT test number

636755004842

Result

✓ Passed

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Brake pipe corroded, covered in grease or other material middle front , above sub frame (1.1.11 (c))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice High rear brake im,balance

Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #19**

2020-02-26 15:39

MOT test number

162759383536

Result

✓ Passed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Minor Offside Headlamp reflector slightly defective (4.1.1 (b) (i))

Advice Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #18

2020-02-26 13:00

MOT test number

976077145394

Result

✗ Failed

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Minor Offside Headlamp reflector slightly defective (4.1.1 (b) (i))

Fail Brakes imbalanced across an axle loud noise from offside rear brake whilst braking (1.2.1 (b) (i))

**MOT #17**

2019-01-25 11:09

MOT test number

486736820956

Result

✓ Passed

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material corroding (1.1.11 (c))
- Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear mounting bush (5.3.4 (a) (i))
- Advice** Offside Rear brake noisy when under load

MOT #16

2018-01-17 12:16

MOT test number

357514443714

Result

✓ Passed

- Advice** Nearside Front Suspension arm has slight play in a pin/bush Rear bush (2.4.G.2)
- Advice** Steering column top bearing slightly worn (2.1.2c)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front out rigger has slight corrosion
- Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)
- Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)
- Advice** Offside Front Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)

**MOT #15** 2018-01-10 12:37**MOT test number** 453252381243**Result** ✗ Failed**Fail** Offside Rear Outer Suspension component mounting prescribed area is excessively corroded suspension arm (2.4.A.3)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush Rear bush (2.4.G.2)**Advice** Steering column top bearing slightly worn (2.1.2c)**Advice** Offside Front Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front out rigger has slight corrosion**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)**Fail** Horn not working (1.6.2a)**MOT #14** 2017-01-12 10:16**MOT test number** 818685480266**Result** ✓ Passed**MOT #13** 2017-01-12 10:16**MOT test number** 649780108157**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #12** 2016-01-18 09:15**MOT test number** 998002526674**Result** ✓ Passed**MOT #11** 2015-01-14 09:15**MOT test number** 777634615060**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Nearside rear tyre starting to perish**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #10** 2014-01-22 10:08**MOT test number** 805982224062**Result** ✓ Passed**Notice** Nearside rear tyre cracking on inner and outer sidewalls**Notice** Offside headlamp poor pattern and damp**Notice** Slight play in both front and both rear wheel bearings**MOT #9** 2013-01-25 11:53**MOT test number** 638935623052**Result** ✓ Passed**Notice** Side wall of nearside rear & offside front tyres perishing (cracks in side wall)**Notice** Nearside front brake pipe at caliper corroded**Notice** High rear brake imbalance**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Poor offside headlamp pattern, damp in light unit

**MOT #8** 2012-01-20 09:25**MOT test number** 997780622013**Result** ✓ Passed**MOT #7** 2011-01-25 09:07**MOT test number** 375075521021**Result** ✓ Passed**MOT #6** 2010-01-18 09:35**MOT test number** 213438310009**Result** ✓ Passed**Notice** Offside rear brake performance lower than nearside**MOT #5** 2009-01-09 09:31**MOT test number** 470749609071**Result** ✓ Passed**MOT #4** 2008-01-25 11:08**MOT test number** 410005528092**Result** ✓ Passed**MOT #3** 2008-01-23 09:44**MOT test number** 580313128036**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Rear Brake hose ferrule excessively corroded (3.6.B.4e)**Fail** Nearside Rear Brake hose ferrule excessively corroded (3.6.B.4e)**Fail** Exhaust emissions carbon monoxide content excessive (7.3.B.1a)



MOT #2	2007-01-25 13:52
MOT test number	573175227054
Result	✓ Passed
MOT #1	2006-01-26 13:22
MOT test number	784076726076
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
14 January 2025

Tax status		Valid until 1 April
Days left		336
MOT expiry date		14 January 2025
Full MOT history		See MOT history



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 F673HNN
Plate since	2024-03-29
Current registration	 F673HNN
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1988-12-01
Last registration	2023-12-22
Complete history	See info



Registration #1	1988-12-01	11 mi
Registration #2	2006-01-26	93.870 mi
Registration #3	2007-01-25	98.063 mi
Registration #4	2008-01-23	101.453 mi
Registration #5	2008-01-25	101.456 mi
Registration #6	2009-01-09	103.777 mi
Registration #7	2010-01-18	108.375 mi
Registration #8	2011-01-25	111.716 mi
Registration #9	2012-01-20	115.538 mi
Registration #10	2013-01-25	118.878 mi
Registration #11	2014-01-22	121.611 mi
Registration #12	2015-01-14	123.520 mi
Registration #13	2016-01-18	125.678 mi
Registration #14	2016-01-18	125.678 mi
Registration #15	2016-01-18	125.678 mi
Registration #16	2016-01-18	125.678 mi
Registration #17	2016-01-18	125.678 mi
Registration #18	2016-01-18	125.678 mi
Registration #19	2016-01-18	125.678 mi
Registration #20	2016-01-18	125.678 mi
Registration #21	2016-01-18	125.678 mi
Registration #22	2016-01-18	125.678 mi
Registration #23	2016-01-18	125.678 mi
Registration #24	2016-01-18	125.678 mi
Registration #25	2016-01-18	125.678 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Additional information

Engine number	DG142155
---------------	----------