



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 CRDI COMFORT
Colour	Blue
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-06-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	9
Total items failed	4

MOT #13	2023-06-22 08:34
MOT test number	603613666100
Result	✓ Passed
Next expiry date	2024-06-21

MOT #12	2022-08-26 09:01
MOT test number	383096379420
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #11	2021-08-04 11:32
MOT test number	765064546629
Result	✓ Passed

MOT #10	2020-07-30 12:06
MOT test number	574253828394
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Front Tyres wearing on edges slightly (advising)
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2019-07-30 10:53**MOT test number** 986415670721**Result** ✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs corroded but not affecting brake performance. (1.1.14 (a) (ii))

**Advice** Front Registration plate deteriorated but not likely to be misread Front number plate cracked. (0.1 (b))

**MOT #8** 2019-07-29 12:00**MOT test number** 582029566591**Result** ✗ Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Tyre cracking/perished. (5.2.3 (d) (ii))

**Advice** Front Registration plate deteriorated but not likely to be misread Front number plate cracked. (0.1 (b))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs corroded but not affecting brake performance. (1.1.14 (a) (ii))

**MOT #7** 2018-07-23 10:31**MOT test number** 304897977000**Result** ✓ Passed**MOT #6** 2017-07-19 10:57**MOT test number** 601592145238**Result** ✓ Passed**MOT #5** 2016-08-02 12:04**MOT test number** 206754925938**Result** ✓ Passed



MOT #4	2015-07-28 11:15
MOT test number	579619305267
Result	✓ Passed
MOT #3	2014-07-10 09:43
MOT test number	829021794121
Result	✓ Passed
MOT #2	2013-07-19 14:10
MOT test number	297160203217
Result	✓ Passed
MOT #1	2013-07-19 14:10
MOT test number	448360903265
Result	✗ Failed
<div>Pass with rectification</div> Nearside Rear Stop lamp not working (1.2.1b)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>YY10OKU</b>
Plate since	2024-03-29
Current registration	<b>YY10OKU</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-08-02
Last registration	2023-06-22
Complete history	<a href="#">See info</a>



Registration #1	2010-08-02	7 mi
Registration #2	2013-07-19	9.594 mi
Registration #3	2014-07-10	16.788 mi
Registration #4	2015-07-28	23.746 mi
Registration #5	2016-08-02	27.830 mi
Registration #6	2017-07-19	32.670 mi
Registration #7	2018-07-23	37.318 mi
Registration #8	2019-06-20	39.377 mi
Registration #9	2019-06-20	39.377 mi
Registration #10	2019-06-20	39.377 mi
Registration #11	2019-06-20	39.377 mi
Registration #12	2019-06-20	39.377 mi
Registration #13	2019-06-20	39.377 mi
Registration #14	2019-06-20	39.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1565 mm
Length	4475 mm
Wheel base	2700 mm
Kerb weight	1442 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBAZ247045