





report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 L LWB P/V 90
Colour	White
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-08

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-30
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	39
Total items failed	13

MOT #18	2024-03-19 16:43
MOT test number	115048821772
Result	✓ Passed
Next expiry date	2025-03-30
Minor Offside Front Lower Windscreen damaged but not adversely affecting driv	er's view (3.2 (a) (i))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Advice Central Front Registration plate deteriorated but not likely to be misread	(0.1 (b))

MOT #17		2023-03-17 15:44
MOT test	number	863346745653
Result		✓ Passed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4	1 (b) (i))
Advice slight mo	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive m vement (5.3.4 (a) (i))	ovement D bush
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5	5.3.4 (b) (i))
Advice	Oil leak, but not excessive Engine area oil leak (8.4.1 (a) (i))	
Advice	Exhaust central rubber mounting broken	
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated	(5.3.4 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material NSR and OSR corro	ded (1.1.11 (c))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #16 2022-03-15 16:41

MOT test number 776081689275

Result ✓ Passed

Minor Front Anti-roll bar linkage ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))

Advice Under body has slight corrosion

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15 2021-03-31 11:32

MOT test number 655344454660

Result ✓ Passed

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Under body corroded

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement de-bushes (5.3.4 (a)

(i))

MOT #14 2019-05-02 12:02

MOT test number 727752681847

Result
✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT test number

Result

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Oil leak

MOT #12 2018-03-16 09:58 **MOT** test number 487350040289 Result × Failed Advice Oil leak **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Nearside Stop lamp not working (1.2.1b) Central Stop lamp not working (1.2.1b) Fail **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Fail Nearside Front Front wheel bearing rough when rotated (2.5.A.2) Fail Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b) Advice Parking brake lever has little reserve travel (3.1.6b) Offside Stop lamp not working (1.2.1b) Fail Nearside Registration plate lamp not working (1.1.C.1d) Fail

MOT #11	2017-02-21 11:41
MOT test number	657270978474
Result	✓ Passed
Advice Oil leak Engine has slight oil leak	

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT test number
908362563167

Result

Pass with rectification
Central Fuel system component leaking Fuel filter connector (7.2.3)

Pass with rectification
Nearside Rear Registration plate lamp not working (1.1.C.1d)

Advice
Oil leak Engine has slight oil leak

MOT #9

MOT test number

634158768392

Result

Advice Slide door not opening able to gain access to rear through two rear doors

MOT #8

MOT test number

Result

Notice Oil leaks at front of engine

2015-02-18 11:03

747339945094

✓ Passed

MOT #7

MOT test number

Result

Pass with rectification
Upper Stop lamp not working (1.2.1b)

Notice
Oil leaks at front of engine

 MOT #6
 2014-03-10 16:25

 MOT test number
 148509664474

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #5 2014-03-07 16:38

MOT test number 115246264472

Result X Failed

Fail Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)

Fail Offside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Headlamp insecure (1.7.3)

MOT #4 2013-03-05 15:51

MOT test number 275644063083

Result
✓ Passed

MOT #3 2012-03-12 09:17

MOT test number 145112472065

Result \(\sqrt{Passed} \)

Advice Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #2 2011-03-15 12:51

MOT test number 867054771027

Result ✓ Passed

MOT #1 2010-03-08 15:33

MOT test number 130277460091

Result
✓ Passed

CarCheck.co.uk page 7/14




report date: 2024-03-28

See MOT history

Tax & MOT check

Full MOT history



CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	AK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-13
Last registration	2024-03-19
Complete history	See info



Registration #1	2007-03-13	6 mi
Registration #2	2010-03-08	41.550 mi
Registration #3	2011-03-15	55.665 mi
Registration #4	2012-03-12	76.126 mi
Registration #5	2013-03-05	86.971 mi
Registration #6	2014-03-07	92.156 mi
Registration #7	2014-03-10	92.184 mi
Registration #8	2015-02-18	96.168 mi
Registration #9	2016-03-18	107.249 mi
Registration #10	2017-02-21	122.840 mi
Registration #11		71.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
60567	
50569	

Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Kerb weight	1399 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	7T48963

CarCheck.co.uk page 14/14