



EKIOAEY

report date: 2024-03-29

General information

Make	FORD
Model	MONDEO EDGE TDCI 140
Colour	Silver
Year of manufacture	-
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



**MOT history**

MOT #14	2022-05-28 11:51
MOT test number	944416023180
Result	✓ Passed
Next expiry date	2023-05-27
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #13	2021-04-01 12:05
MOT test number	400868726665
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
Advice	Surface corrosion on underside of vehicle front to rear
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #12**

2021-03-12 17:02

MOT test number

180722645603

Result**✗ Failed**

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
- Fail** Main beam tell-tale not working (4.9.1 (a) (ii))
- Fail** Rear Exhaust system insecure Back box bracket broken (6.1.2 (a))
- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Offside Rear Outer tail lamp inoperative inner still working
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Rear Rear fog lamp not working Tell tale also not working (4.5.1 (a) (ii))
- Advice** Surface corrosion on underside of vehicle front to rear
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))

**MOT #11** 2020-03-14 10:49**MOT test number** 800090077791**Result** ✓ Passed

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10 2020-03-14 09:32**MOT test number** 277954198877**Result** ✗ Failed

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Pitted on inside face (1.1.14 (a) (ii))
- Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

MOT #9 2019-03-21 15:29**MOT test number** 313815484292**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MOT #8**

2019-03-20 11:10

MOT test number

812935174703

Result**✗ Failed****Advice** Rear Exhaust mounting defective (6.1.2 (a))**Fail** Suspension arm pin or bush excessively worn both rear trailing arm bushed deteriorated (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Headlamp aim projected beam image is obviously incorrect headlight not seated correctly (4.1.2 (c))**MOT #7**

2018-02-19 15:15

MOT test number

713929738498

Result**✓ Passed****Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Direction indicators slightly discoloured both (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6**

2018-02-19 14:27

MOT test number

753032652247

Result**✗ Failed****Fail** Horn not working (1.6.2a)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Items removed from driver's view prior to test sat nav**Advice** Rear Direction indicators slightly discoloured both (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #5** 2017-02-07 15:17**MOT test number** 846605634107**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-02-12 11:40**MOT test number** 236807080301**Result** ✓ Passed**MOT #3** 2015-03-18 06:41**MOT test number** 688577075074**Result** ✓ Passed**Notice** Right front tyre wearing inner edge**MOT #2** 2014-03-10 07:20**MOT test number** 349719064050**Result** ✓ Passed**MOT #1** 2013-03-25 08:03**MOT test number** 146404383432**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK10AEY
Plate since	2019-03-29
Current registration	EK10AEY
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-23
Last registration	2022-05-28
Complete history	See info



Registration #1	2010-03-23	25 mi
Registration #2	2013-03-25	22.604 mi
Registration #3	2014-03-10	31.944 mi
Registration #4	2015-03-18	41.700 mi
Registration #5	2016-02-12	49.543 mi
Registration #6	2017-02-07	60.108 mi
Registration #7	2018-02-19	67.301 mi
Registration #8	2018-02-19	67.301 mi
Registration #9	2019-05-28	67.301 mi
Registration #10	2020-05-28	67.301 mi
Registration #11	2021-05-28	67.301 mi
Registration #12	2022-05-28	67.301 mi
Registration #13	2023-05-28	67.301 mi
Registration #14	2024-05-28	67.301 mi
Registration #15	2025-05-28	67.301 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1557 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AS61625