





## General information

Make	ΤΟΥΟΤΑ
Model	RAV-4 VVT-I XT3
Colour	Green
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	10.8 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	37.2 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	Κ







# Internet history

Entry 2	
Date	2021-08-12
Pictures	24
Listing price	View report



source: cargurus.co.uk

#### Entry 1

Date	2021-08-11
Pictures	0
Listing price	View report

source: autotrader.co.uk



# MOT history

MOT expiry date	2024-08-29
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	28
Total items failed	4

MOT #19	2023-08-30 11:19
MOT test number	764973696573
Result	✓ Passed
Next expiry date	2024-08-29
Advice ALL REAR BUSHES PERISHED	
Advice SURFACE RUST UNDER VEHICLE	

MOT #18	2022-08-13 17:40
MOT test number	937828676811
Result	✓ Passed
<b>Advice</b> Headlamp has a product on the light source but not seriously reducing light of (4.1.4 (b))	utput Both side
Advice Front Suspension arm corroded but not seriously weakened Both side (5.3.3 (	b) (i))
<b>Advice</b> Rear Suspension component mounting prescribed area is corroded but not con Both side (5.3.6 (a) (i))	nsidered excessive
Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorate	ed (5.3.4 (b) (i))
Advice Front Suspension arm pin or bush worn but not resulting in excessive moveme (a) (i))	ent Both side (5.3.4
Advice Rear Suspension arm corroded but not seriously weakened Both side (5.3.3 (b	)) (i))
Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b	) (i))





MOT #17	2021-08-11 16:16
MOT test number	746044017353
Result	✓ Passed
MOT #16	2020-11-20 09:51
MOT test number	446714910235
Result	✓ Passed

MOT #15	2	019-05-21 13:16
MOT test	number	137692859406
Result		🗸 Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	)

MOT #14	2019-05-20 10:51
MOT test number	104780768841
Result	🗙 Failed
<b>Fail</b> Nearside Front Track rod end ball joint dust cover insecure so that it no longer previdirt (2.1.3 (g) (ii))	ents the ingress of
FailNearside Rear Rear reflector defective or damaged by more than 50% of the reflect(a) (ii))	ing surface (4.8.1
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c	))
<b>Fail</b> Offside Front Track rod end ball joint dust cover insecure so that it no longer prever dirt (2.1.3 (g) (ii))	nts the ingress of
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #13	2018-05-11 08:06
MOT test number	225198392690
Result	✓ Passed



GP	04	U	F	D
repo	rt date	: 20	24-0	3-29

MOT #12		2017-06-01 07:53
MOT test	number	933150824243
Result		✓ Passed
Advice	Exhaust corroded	
Advice	No rear seats fitted	
MOT #11		2016-05-09 13:44
MOT test	number	724567969223
Result		Passed
Advice	Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)	
Advice	Unable to carry out full inspection of rear seatbelts . no rearseats fitted at tir	me of test
Advice	Nearside Rear Shock absorber has a slightly worn bush upper and lower bush	hes perished (2.7.4)
<b>Advice</b> Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)		
Advice	Offside Front Inner Brake pad(s) wearing thin (3.5.1g)	
Advice	Exhaust system rusty	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Offside Rear Shock absorber has a slightly worn bush upper and lower bushe	es perished (2.7.4)

MOT #10	2015-06-26 08:17
MOT test number	336037175115
Result	✓ Passed

MOT #9	2014-06-13 10:37
MOT test number	219434264498
Result	✓ Passed
Notice Vehicle's internal headlight adjuster altered to recheck lights	



GP04UFD report date: 2024-03-29

MOT #8		2014-06-13 10:37
MOT test number		995654164128
Result		🗙 Failed
Notice Vehicle's interna	l headlight adjuster altered to recheck lights	
Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)		

MOT #7	2013-06-04 11:22
MOT test number	228785253163
Result	✓ Passed
Notice Exhaust tailpipe fixing bolts corroded	

MOT #6	2012-06-07 12:49
MOT test number	738009052183
Result	✓ Passed

MOT #5	2011-06-14 12:23
MOT test number	415135561140
Result	✓ Passed

МОТ #4	2010-05-12 13:44
MOT test number	971552130171
Result	✓ Passed

MOT #3		2009-05-26 11:28
MOT test	number	533476149165
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	





MOT #2	2008-06-06 10:01
MOT test number	604188258138
Result	✓ Passed
MOT #1	2007-06-05 08:49
MOT test number	393196457166
Result	✓ Passed



Tax & MOT check

√ Taxed	√ мот
<b>Tax due:</b> 1 September 2024	Expires: 29 August 2024
Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

4
AMP
- A

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
**********	
********	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



GP04UFD report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-05-25
Last registration	2023-08-30
Complete history	See info



Registration #1	2004-05-25	12 mi
Registration #2	2007-06-05	24.376 mi
Registration #3	2008-06-06	33.686 mi
Registration #4	2009-05-26	42.239 mi
Registration #5	2010-05-12	45.810 mi
Registration #6	2011-06-14	50.863 mi
Registration #7	2012-06-07	54.854 mi
Registration #8	2013-06-04	58.141 mi
Registration #9	2014-06-13	65.172 mi
Registration #10	2015-06-26	69.274 mi
Registration #11	2016-05-09	73.435 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 esi

More info >





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg
Additional information	
Fuel tank capacity	57
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	1AZ1358652