



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 D2 R-DESIGN NAV PLUS
Colour	White
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	83.1 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #5	2023-06-02 12:35
MOT test number	544637521416
Result	✓ Passed
Next expiry date	2024-06-01

MOT #4	2022-05-27 10:10
MOT test number	681631223187
Result	✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2021-06-02 14:30**MOT test number** 493617850102**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #2** 2020-09-02 09:05**MOT test number** 427749111022**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords 3 cuts on outer sidewall (5.2.3 (d) (i))**MOT #1** 2020-09-01 13:40**MOT test number** 488395969146**Result** ✗ Failed**MAJOR** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords 3 cuts on outer sidewall (5.2.3 (d) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
1 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	1 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>First licence fee (12 months)</b>	£ 165,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 185,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>DK67USU</b>
Plate since	2019-03-29
Current registration	<b>DK67USU</b>
Plate since	2019-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-01
Last registration	2023-06-02
Complete history	<a href="#">See info</a>



Registration #1	2017-09-01	24 mi
Registration #2	2020-09-01	14.948 mi
Registration #3	2020-09-02	14.948 mi
Registration #4	2020-09-02	14.948 mi
Registration #5	2020-09-02	14.948 mi
Registration #6	2020-09-02	14.948 mi
Registration #7	2020-09-02	14.948 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1382 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	2060052
---------------	---------