



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN

**MOT history****MOT #13** 2020-06-12 11:10**MOT test number** 951063336631**Result** ✓ Passed**Next expiry date** 2021-06-11

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front suspension arm rear bushes (5.3.4 (a) (i))

Advice Both front tyres wearing on edges

Advice Brake disc worn, pitted or scored, but not seriously weakened both front pitting on inner surfaces (1.1.14 (a) (ii))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #12 2020-06-11 15:44**MOT test number** 638760398174**Result** ✗ Failed

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Fail Offside Rear Inner Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Both front tyres wearing on edges

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front suspension arm rear bushes (5.3.4 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front pitting on inner surfaces (1.1.14 (a) (ii))

Fail Nearside Rear Brake lever has restricted free movement handbrake lever on caliper stuck on (1.1.15 (e))

**MOT #11**

2019-05-17 09:29

MOT test number

779414263100

Result

✓ Passed

- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10

2019-05-16 08:06

MOT test number

458847426657

Result

✗ Failed

- Fail** Nearside Rear Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #9

2018-05-23 11:20

MOT test number

281129453098

Result

✓ Passed

- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush splitting (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush splitting (5.3.4 (a) (i))

**MOT #8** 2017-05-09 14:59**MOT test number** 601743828577**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-05-26 13:04**MOT test number** 505346247718**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2015-06-12 10:06**MOT test number** 516413065195**Result** ✓ Passed**Advice** Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2014-07-03 16:07**MOT test number** 147954184100**Result** ✓ Passed**MOT #4** 2013-10-24 12:31**MOT test number** 365607393266**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)



MOT #3	2012-11-08 15:05
MOT test number	415653712330
Result	✓ Passed

MOT #2	2012-11-08 15:05
MOT test number	598693912398
Result	✗ Failed
<div>Pass with rectification</div> Front Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #1	2011-10-28 15:29
MOT test number	187041301346
Result	✓ Passed
<div>Advice</div> Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-10-31
Last registration	2020-06-12
Complete history	See info



Registration #1	2008-10-31	15 mi
Registration #2	2011-10-28	29.998 mi
Registration #3	2012-11-08	37.903 mi
Registration #4	2013-10-24	45.296 mi
Registration #5	2014-07-03	49.709 mi
Registration #6	2015-06-12	60.671 mi
Registration #7	2016-05-26	71.377 mi
Registration #8	2017-05-29	81.377 mi
Registration #9	2018-05-29	91.377 mi
Registration #10	2019-05-29	101.377 mi
Registration #11	2020-05-29	111.377 mi
Registration #12	2021-05-29	121.377 mi
Registration #13	2022-05-29	131.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8R43181