





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2016
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP	
Engine capacity	1.242 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	42.2 mpg	
Consumption extra urban	65.7 mpg	
Consumption combined	54.3 mpg	
CO2 emission	119 g/km	
CO2 label	С	



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-09

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-19
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	17
Total items failed	1

MOT #8	2023-12-06 09:47
MOT test number	969357249044
Result	✓ Passed
Next expiry date	2024-12-19
Advice Front Brakes imbalanced requirements only just met. It would appear that requires adjustment or repair. (1.2.1 (b) (i))	the braking system
Advice Exhaust minor blow	
Advice Front Lower Suspension arm pin or bush worn but not resulting in excessiv (5.3.4 (a) (i))	re movement both

MOT #7	2022-12-07 09:49
MOT test number	489249924252
Result	✓ Passed
MOT #6	2021-12-20 14:57
MOT test number	890455619708
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2021-01-28 15:38 **MOT test number** 960723475081 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Parking brake requires large effort Advice Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4		2021-01-26 16:54
MOT test	number	259914824396
Result		× Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Parking brake requires large effort	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2020-01-22 15:29
MOT test Result	number 668407494653 ✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2 2019-01-17 15:29

MOT test number 840589873343

MOT #1 2019-01-17 15:29

MOT test number 537906432252

Result X Failed

Pass with rectification Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



✓ MOT

Expires: 19 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

^ -		histor	-
- () ()	vnor	nictor	٦.
\smile	VIICI	пизсоп	·v

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-01-26
Last registration	2023-12-06
Complete history	See info



Registration #1	2016-01-26	15 mi
Registration #2	2019-01-17	24.151 mi
Registration #3	2019-01-17	24.151 mi
Registration #4	2020-01-22	31.716 mi
Registration #5	2021-01-26	36.319 mi
Registration #3	2021-01-20	301313 1111
Registration #6	2021-01-20	8 m m
	2021-01-20	11.777 ess
Registration #6	2021-01-20	9 70 mi
Registration #6 Registration #7	2021-01-20	9.77 m

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number Carcheck.co.uk	1523903 page 12/12