





report date: 2024-03-29

### General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI SE
Colour	Silver
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-06-19

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



**MOT** history

MOT #18 2022-10-25 10:44

MOT test number 510057005986

**Result** ✓ Passed

Next expiry date 2023-10-24

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear bumper damaged

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2022-10-25 10:44

**MOT test number** 623935318101

**Result** X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear bumper damaged

MOT #16 2021-08-24 14:00

MOT test number 336573657401

Result \( \sqrt{Passed} \)

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/13



MOT #15 2021-08-24 14:00

MOT test number 343239870371

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #14** 2020-10-30 16:09

**MOT test number** 543071708045

Result \( \sqrt{Passed} \)

MOT #13 2020-10-30 11:16

**MOT test number** 653864623061

**Result** X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2019-11-08 09:59

MOT test number 920379375506

Result 

Passed

**Minor** Front Tyre obviously under inflated both (5.2.3 (I))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** O/s/f tyre worn edges

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11 2018-11-20 11:23

MOT test number 410446058949

Result Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10 2017-11-10 09:38

MOT test number 221193697985

**Result** 
✓ Passed

**Advice** Offside Front inner tie rod slight play

**Advice** Nearside Front inner tie rod slight play

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #9 2016-11-18 14:22

MOT test number 162092684848

**Result** ✓ Passed

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #8 2016-11-15 10:10

MOT test number 143307309127

**Result** X Failed

**Advice** Offside Rear Tyre worn close to the legal limit uneven on inside edge (4.1.E.1)

**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)

**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)

**Advice** Nearside Rear Tyre worn close to the legal limit uneven on inside edge (4.1.E.1)

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

**Advice** Offside Front Tyre worn close to the legal limit both edges (4.1.E.1)

**Advice** Both rear tyres deteriorated , no ply or cords visible

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #7

MOT test number

Result

Advice Both rear tyres have some degree of age related cracking.

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT test number

Result

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Nearside Rear coil spring broken (2.4.C.1a)

Advice Both rear tyres have some degree of age related cracking.

MOT test number

Result

Advice Nearside Brake pipe slightly corroded (3.6.B.2c)

Notice Under-trays fitted obscuring some underside components

Advice Offside Brake pipe slightly corroded (3.6.B.2c)

Notice Both rear tyres cracking in tread

 MOT #4
 2013-11-06 16:27

 MOT test number
 225680413380

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



MOT test number
938509673165

Result

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #2	2012-07-13 13:19
MOT test number	467405192125
Result	<b>✓</b> Passed
MOT #1	2011-07-14 11:02
MOT test number	618385391125
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/13




report date: 2024-03-29

#### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES-BENZ salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

$\sim$		100	
Owi	ner	nıs	torv

e mier metery	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report <a href="https://example.com/here">here</a> .	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
Current registration	NK SIL
Plate since	
Current registration	NK NK
Plate since	

CarCheck.co.uk page 10/13



#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-07-24
Last registration	2022-10-25
Complete history	See info



Registration #1	2008-07-24	27 mi
Registration #2	2011-07-14	42.102 mi
Registration #3	2012-07-13	52.221 mi
Registration #4	2013-06-28	63.097 mi
Registration #5	2013-11-06	64.707 mi
Registration #6	2014-10-20	73.009 mi
Registration #7	2015-11-20	82.664 mi
Registration #8	2015-11-23	82.664 mi
Registration #9	2016-11-15	91.403 mi
Registration #10	2016-11-18	91.408 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777-es

More info >

CarCheck.co.uk page 12/13



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg

## Additional information

Fuel tank capacity	54 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

CarCheck.co.uk page 13/13

Number of axles 2

**Engine number** 64094030438705