





General information

Make	VOLKSWAGEN
Model	AMAROK DC V6 TDI HIGHLINE 4MOTION
Colour	Black
Year of manufacture	2018
Top speed	119 mph
0 - 60 mph	8.0 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 2.750 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	37.2 mpg
Consumption combined	34.9 mpg
CO2 emission	204 g/km
CO2 label	Κ





BD05LTD report date: 2024-03-29

Internet history


Entry 6 Date

Pictures

Listing price

11 View report

2022-01-27



source: cargurus.co.uk

Entry 5	
Date	2022-01-26
Pictures	11
Listing price	View report



source: autotrader.co.uk

Entry 4

Date	2021-11-03
Pictures	12
Listing price	View report



source: cargurus.co.uk

PICTURES

Listing price

0

View report

source: heycar.co.uk

Entry 2

Date	2021-10-09
Pictures	20
Listing price	<u>View report</u>



source: autotrader.co.uk

Entry 1

Date	2021-07-21
Pictures	20
Listing price	View report



source: autotrader.co.uk









MOT history

MOT expiry date	2025-04-08
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #5	2024-04-09 11:24
MOT test number	825802046544
Result	✓ Passed
Next expiry date	2025-04-08
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #4		2023-02-24 11:30
MOT test	number	432181517097
Result		✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2022-03-15 16:07
MOT test number	935793727594
Result	✓ Passed





MOT #2	2021-11-13 10:31
MOT test number	312041275317
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #1	2021-03-26 16:15
MOT test number	520215475661
Result	✓ Passed



Tax & MOT check

✓ Taxed	мот
Tax due: 1 November 2024	Expires: 8 April 2025
Tax status	Valid until 1 November
Days left	187
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY ANY ANY ANY ANY ANY ANY ANY ANY ANY AN	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



BD05LTD report date: 2024-03-29

Mileage check

Mileage registrations12First mileage registration2018-03-28Last registration2024-04-09Complete historySee info
Last registration2024-04-09
-
Complete history See info



Registration #1	2018-03-28	28 mi
Registration #2	2021-03-26	41.111 mi
Registration #3		11.117 esi
Registration #4		11.117 esi
Registration #5		11.177 esi
Registration #6		11.177 esi
Registration #7		11.177 esi
Registration #8		11.177 esi
Registration #9		11.777 esi
Registration #10		11.777 esi
Registration #11		11.177 esi
Registration #12		11.777 est





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating	
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



Dimensions & weight	
Width	2228 mm
Height	1834 mm
Length	5254 mm
Kerb weight	2176 kg
Max. allowed weight	3290 kg
Additional information	
Free Lands and a Star	

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarCheck.co.uk	page 11/11