



Mercedes-Benz

 **J15LCN**

report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B170 SE
Colour	Silver
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	114 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.699 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	171 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-09-15
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-13
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-03
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	12
Total items failed	8

MOT #20	2023-11-02 11:13
MOT test number	947597512801
Result	✓ Passed
Next expiry date	2024-11-03
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. nearside and offside (1.4.2 (a) (i))

MOT #19	2022-10-04 10:17
MOT test number	573370334274
Result	✓ Passed

MOT #18	2021-11-04 13:59
MOT test number	254568567590
Result	✓ Passed

**MOT #17** 2021-11-01 18:19**MOT test number** 378610027099**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2020-08-12 11:22**MOT test number** 383902968271**Result** ✓ Passed**MOT #15** 2019-09-04 10:19**MOT test number** 687465817460**Result** ✓ Passed**MOT #14** 2019-09-03 08:31**MOT test number** 701756956176**Result** ✗ Failed**Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**MOT #13** 2018-08-23 07:27**MOT test number** 542777744571**Result** ✓ Passed

**MOT #12** 2017-08-29 15:38**MOT test number** 772430870916**Result** ✓ Passed**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**MOT #11** 2017-08-29 08:03**MOT test number** 513629737269**Result** ✗ Failed**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**Fail** Nearside Brake pipe excessively corroded front to rear (3.6.B.2c)**MOT #10** 2016-09-07 13:06**MOT test number** 173309067615**Result** ✓ Passed**Advice** Brake pipe slightly corroded front to rears (3.6.B.2c)**MOT #9** 2016-09-07 10:01**MOT test number** 262748041356**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Brake pipe slightly corroded front to rears (3.6.B.2c)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #8** 2015-08-19 07:35**MOT test number** 439311567429**Result** ✓ Passed



MOT #7	2015-08-18 00:00
---------------	------------------

MOT test number	719537999270
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2014-09-01 11:33
---------------	------------------

MOT test number	725914144249
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Road wheel slightly damaged (4.2.A.1a)
---------------	--

MOT #5	2013-08-23 11:10
---------------	------------------

MOT test number	108005633208
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2012-09-07 11:17
---------------	------------------

MOT test number	819611452203
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-09-07 11:17
---------------	------------------

MOT test number	746761852244
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Front Headlamp aim too high (1.8)
--------------------------------	--

MOT #2	2012-05-28 16:51
---------------	------------------

MOT test number	488189142111
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2012-01-16 15:34
---------------	------------------

MOT test number	675546212055
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
3 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-02-19
Last registration	2023-11-02
Complete history	See info



Registration #1	2009-02-19	17 mi
Registration #2	2012-01-16	20.671 mi
Registration #3	2012-05-28	21.815 mi
Registration #4	2012-09-07	23.256 mi
Registration #5	2013-08-23	33.140 mi
Registration #6	2014-09-01	43.818 mi
Registration #7	2015-08-18	45.768 mi
Registration #8	2015-08-19	45.768 mi
Registration #9	2016-09-07	47.346 mi
Registration #10	2016-09-07	47.346 mi
Registration #11	2017-08-29	48.058 mi
Registration #12	2019-05-29	51.277 mi
Registration #13	2019-05-29	51.277 mi
Registration #14	2019-05-29	51.277 mi
Registration #15	2019-05-29	51.277 mi
Registration #16	2019-05-29	51.277 mi
Registration #17	2019-05-29	51.277 mi
Registration #18	2019-05-29	51.277 mi
Registration #19	2019-05-29	51.277 mi
Registration #20	2019-05-29	51.277 mi
Registration #21	2019-05-29	51.277 mi
Registration #22	2023-11-02	51.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1310 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	26694030584764