



GVI3VSO

report date: 2024-03-28

General information

Make	FORD
Model	FIESTA TDCI STYLE
Colour	Black
Year of manufacture	2013
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	159 Nm at 2.000 rpm
Engine capacity	1.499 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2021-10-27
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-09
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-10
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	21
Total items failed	0

MOT #9	2023-06-07 15:46
MOT test number	554822139146
Result	✓ Passed
Next expiry date	2024-06-10

MOT #8	2023-06-07 13:28
MOT test number	509390003119
Result	✗ Failed
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
DANGEROUS	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #7	2022-05-25 15:25
MOT test number	384944219260
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #6** 2022-05-25 08:32**MOT test number** 428788671467**Result** ✗ Failed**MAJOR** Exhaust emissions exceed manufacturer's specified limit Plate limit 0.54 (8.2.2.2 (a))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MAJOR** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MOT #5** 2021-06-03 12:40**MOT test number** 775886543908**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn close to the cords on the inner edge (5.2.3 (e))**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #4** 2021-06-01 15:12**MOT test number** 283201122319**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn close to the cords on the inner edge (5.2.3 (e))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #3** 2020-06-11 12:12**MOT test number** 688345280020**Result** ✓ Passed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Road wheel slightly distorted inner side (5.2.2 (c) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2019-06-17 14:40**MOT test number** 592663595244**Result** ✓ Passed**MOT #1** 2018-07-18 11:13**MOT test number** 745023038718**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 June
-------------------	--------------------

Days left	34
------------------	----

MOT expiry date	10 June 2024
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	GV13VSO
Plate since	2019-09-28
Current registration	GV13VSO
Plate since	2019-09-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-31
Last registration	2023-06-07
Complete history	See info



Registration #1	2013-12-31	9 mi
Registration #2	2018-07-18	39.538 mi
Registration #3	2019-06-17	54.096 mi
Registration #4	2020-06-11	57.686 mi
Registration #5	2021-06-01	65.460 mi
Registration #6	2021-06-03	65.462 mi
Registration #7	2023-06-07	65.462 mi
Registration #8	2023-06-07	65.462 mi
Registration #9	2023-06-07	65.462 mi
Registration #10	2023-06-07	65.462 mi
Registration #11	2023-06-07	65.462 mi
Registration #12	2023-06-07	65.462 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	86%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1463 mm
Length	3916 mm

Additional information

Number of seats	5
Number of axles	2
Engine number	NOT KNOWN