



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T230 HR P/V
Colour	Blue
Year of manufacture	2011
Top speed	10 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	1.0 mpg
Consumption extra urban	1.0 mpg
Consumption combined	1.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-10
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	65
Total items failed	6

MOT #142023-05-10 08:37

MOT test number317000483806

Result✓ Passed

Next expiry date2024-05-09

- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice

N/S/R outer sill corroded through

**MOT #13**

2023-05-05 09:06

MOT test number

116610224766

Result**✗ Failed**

- MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- MAJOR** Nearside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** N/S/R outer sill corroded through
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Offside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #12

2022-01-14 10:13

MOT test number

798003888724

Result**✓ Passed**

- Advice** Rear Brake pipe corroded, covered in grease or other material o/s n/s (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11**

2022-01-14 10:12

MOT test number

232643537159

Result**✗ Failed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Rear Brake pipe corroded, covered in grease or other material o/s n/s (1.1.11 (c))

MOT #10

2021-01-15 09:42

MOT test number

612885365178

Result**✓ Passed****Advice**

Offside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))

Advice

Rear Exhaust has a minor leak of exhaust gases silencer to pipe (6.1.2 (a))

**MOT #9** 2021-01-14 09:15**MOT test number** 644676654730**Result** ✗ Failed**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))**MAJOR** Nearside Front Brake disc significantly and obviously worn inner surface (1.1.14 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))**DANGEROUS** Front Brakes imbalanced across an axle by more than 50% 70% Offside slow to apply (1.2.1 (b) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases silencer to pipe (6.1.2 (a))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Central Stop light not working**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))**MOT #8** 2019-07-06 10:30**MOT test number** 706379022037**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #7** 2019-07-06 10:30**MOT test number** 408440491381**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #6** 2018-06-30 09:52**MOT test number** 466569155005**Result** ✓ Passed**Advice** Inner wheel arch liners fitted obscuring some components/prescribed areas**Advice** Front Registration plate deteriorated but not likely to be misread ADVISE REPLACEMENT SOON (0.1 (b))**Advice** Power steering component has slight seepage from a component Steering rack damp around pinion area (2.1.5 (a))**Advice** Brake pipe corroded, covered in grease or other material surface corrosion to all rear pipes (1.1.11 (c))**MOT #5** 2017-06-29 11:49**MOT test number** 269651965737**Result** ✓ Passed**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #4**

2016-07-05 14:48

MOT test number

911540057615

Result

✓ Passed

- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Front Inner Tyre worn close to the legal limit edge . strong advise replacement. (4.1.E.1)
- Advice** Nearside Front Inner Tyre worn close to the legal limit edge . strong advise replacement. (4.1.E.1)
- Advice** Inner wheel arch covers fitted.

MOT #3

2016-07-05 09:37

MOT test number

449104811758

Result

✗ Failed

- Advice** Inner wheel arch covers fitted.
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Fail** Fuel tank leaking (7.2.3)
- Advice** Offside Front Inner Tyre worn close to the legal limit edge . strong advise replacement. (4.1.E.1)
- Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)
- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Inner Tyre worn close to the legal limit edge . strong advise replacement. (4.1.E.1)

MOT #2

2015-03-23 09:56

MOT test number

916852285008

Result

✓ Passed

- Notice** O/s front tyre wearing on inner edge
- Notice** N/s front tyre wearing on inner edge



MOT #1	2014-03-10 16:39
MOT test number	506509864045
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
9 May 2024

Tax status	Valid until 1 June
-------------------	--------------------

Days left	33
------------------	----

MOT expiry date	9 May 2024
------------------------	------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-30
Last registration	2023-05-10
Complete history	See info



Registration #1	2011-03-30	28 mi
Registration #2	2014-03-10	22.681 mi
Registration #3	2015-03-23	30.405 mi
Registration #4	2016-07-05	36.580 mi
Registration #5	2016-07-05	36.580 mi
Registration #6	2017-06-29	42.174 mi
Registration #7	2018-06-30	50.584 mi
Registration #8	2019-07-06	59.269 mi
Registration #9	2020-05-20	65.377 mi
Registration #10	2020-05-20	65.377 mi
Registration #11	2020-05-20	65.377 mi
Registration #12	2020-05-20	65.377 mi
Registration #13	2020-05-20	65.377 mi
Registration #14	2020-05-20	65.377 mi
Registration #15	2020-05-20	65.377 mi
Registration #16	2023-05-10	65.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	1980 mm
Length	4525 mm
Kerb weight	1438 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Number of axles	2
Engine number	AG11065