





report date: 2024-03-28

### General information

Make	LAND ROVER
Model	RANGE ROVER TDV6 VOGUE
Colour	Black
Year of manufacture	2017
Top speed	130 mph
0 - 100 km/h	7.9 seconds
0 - 60 mph	7.4 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	190 kW / 259 HP / 255 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.9 mpg
CO2 emission	182 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-28

#### Internet history

#### Entry 2

Date 2021-12-09

Pictures 12

Listing price View report









source: cargurus.co.uk

#### Entry 1

Listing price

Date	2021-12-07
Pictures	18

View report









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

140	
10/1/1	Γ history
י אועו	1 11151017

MOT expiry date	2024-12-22
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #7	2023-12-22 12:05
MOT test number	896221142377
Result	✓ Passed
Next expiry date	2024-12-22

MOT #6	2022-12-12 13:44
MOT test number	756824963185
Result	<b>✓</b> Passed

MOT #5	2021-12-23 15:59
MOT test number	701864685498
Result	<b>✓</b> Passed

MOT #4	2021-10-22 12:58

**MOT test number** 342911630832

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2021-10-14 08:33

MOT test number 958577699564

Result X Failed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2020-10-04 13:19

**MOT test number** 460162372700

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2020-10-04 13:19

MOT test number 612073528525

Result × Failed

**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))

**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



#### Tax & MOT check



MOT

Tax expired: 22 March 2024

Expires: 22 December 2024

Tax status	Expired at 22 March 2024
Days left	37 days too late
MOT expiry date	22 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28


#### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



#### Extra LAND ROVER salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this LAND ROVER? How many or ROVER have? Check it in the premium report and see all owner registrations. Download to	
THE PARTY OF THE P	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-10-16
Last registration	2023-12-22
Complete history	See info



Registration #1	2017-10-16	7 mi
Registration #2	2020-10-04	47.469 mi
Registration #3	2020-10-04	47.469 mi
Registration #4	2021-10-14	52.665 mi
Registration #5	2021-10-22	52.667 mi
Registration #6		11.777 es
Registration #6 Registration #7		11,777 es
•		11.777 ea 11.777 ea
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	see crash video



# Dimensions & weight

Width	2073 mm
Height	1835 mm
Length	4998 mm
Wheel base	2922 mm
Kerb weight	2160 kg
Max. allowed weight	3050 kg

## Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1112818306DT

CarCheck.co.uk page 11/11