



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D3 SE LUX AWD
Colour	Gold
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-11-01
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	21
Total items failed	2

MOT #12	2023-10-24 11:58
MOT test number	648538817004
Result	✓ Passed
Next expiry date	2024-10-24

MOT #11	2022-10-25 12:02
MOT test number	880341806712
Result	✓ Passed

MOT #10	2022-10-22 08:12
MOT test number	756739524608
Result	✗ Failed

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure out of shape (5.2.3 (d) (ii))

MOT #9	2021-10-20 14:49
MOT test number	651076238097
Result	✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Under trays fitted

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2020-10-16 12:38

MOT test number

749425635216

Result

✓ Passed

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Driver's view to the sides outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7**

2020-10-16 10:44

MOT test number

825957386696

Result

✗ Failed

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Driver's view to the sides outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #6**

2019-10-22 15:35

MOT test number

153647879116

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge, 3mm (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn inner edge, 3mm (5.2.3 (e))**MOT #5**

2018-11-30 11:34

MOT test number

548359989220

Result

✓ Passed

**MOT #4** 2018-01-04 13:54**MOT test number** 721587786652**Result** ✓ Passed**MOT #3** 2016-12-01 14:56**MOT test number** 560986382094**Result** ✓ Passed**Advice** Service light on**Advice** Front lower arm rear bushes starting to split**MOT #2** 2016-12-01 12:44**MOT test number** 317707670088**Result** ✗ Failed**Advice** Front lower arm rear bushes starting to split**Fail** Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Service light on**Advice** Front tyres wearing on inner edges**Fail** Nearside Rear Outer Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #1** 2015-12-01 09:59**MOT test number** 684845714605**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-12-24
Last registration	2023-10-24
Complete history	See info



Registration #1	2012-12-24	24 mi
Registration #2	2015-12-01	33.869 mi
Registration #3	2016-12-01	44.299 mi
Registration #4	2016-12-01	44.299 mi
Registration #5	2018-01-04	70.391 mi
Registration #6	2018-11-30	97.070 mi
Registration #7	2019-10-22	124.299 mi
Registration #8	2020-05-20	151.577 mi
Registration #9	2020-05-20	151.577 mi
Registration #10	2020-05-20	151.577 mi
Registration #11	2020-05-20	151.577 mi
Registration #12	2020-05-20	151.577 mi
Registration #13	2020-05-20	151.577 mi
Registration #14	2020-05-20	151.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1133407