



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | 5 TS2 |
| Colour | Silver |
| Year of manufacture | 2008 |
| Top speed | 121 mph |
| 0 - 60 mph | 10.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 146 BHP |
| Max. torque | 185 Nm at 4.000 rpm |
| Engine capacity | 1.999 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.7 mpg |
| Consumption extra urban | 44.8 mpg |
| Consumption combined | 35.8 mpg |
| CO2 emission | 187 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-11-07 |
| Pictures | 13 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-12 |
| MOT pass rate | 61 % |
| MOT passed | 14 |
| Failed MOT tests | 9 |
| Total advice items | 32 |
| Total items failed | 32 |

| | |
|------------------|---|
| MOT #23 | 2023-12-13 08:56 |
| MOT test number | 341396998343 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-12 |
| Advice | Rear Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a)) |
| Advice | Superficial corrosion to underside but not to excess |

| | |
|-----------------|---|
| MOT #22 | 2023-12-12 14:17 |
| MOT test number | 974424049784 |
| Result | ✗ Failed |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |
| Fail | Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i)) |
| Advice | Rear Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a)) |
| Fail | Offside Front Position lamp not working (4.2.1 (a) (ii)) |
| Advice | Superficial corrosion to underside but not to excess |
| Fail | Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i)) |



MOT #21

2022-11-23 16:27

MOT test number

472860244805

Result

✓ Passed

- Advice

Rear Exhaust has a minor leak of exhaust gases tailpipe (6.1.2 (a))
- Advice

Superficial corrosion on underside / suspension but not to excess
- Advice

Car only just met emission requirements after several attempts, lambda
- Advice

Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Both rear brake backplates corroded and incomplete
- Advice

Fuel filler pipes corroded but not to excess

**MOT #20**

2022-11-21 10:20

MOT test number

241054821469

Result**✗ Failed****Fail** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))**Advice** Car only just met emission requirements after several attempts, lambda**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**Advice** Both rear brake backplates corroded and incomplete**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Fuel filler pipes corroded but not to excess**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases tailpipe (6.1.2 (a))**Advice** Superficial corrosion on underside / suspension but not to excess**MOT #19**

2021-11-16 14:00

MOT test number

530806309165

Result**✓ Passed****Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Upper Fuel Pipe/s corroded**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #18**

2021-11-12 16:07

MOT test number

910921999805

Result**✗ Failed****Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Upper Fuel Pipe/s corroded**Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #17**

2021-01-18 16:18

MOT test number

959220620135

Result**✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (trailing arm) (5.3.4 (a) (i))**MOT #16**

2021-01-18 10:23

MOT test number

283365903649

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (trailing arm) (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Suspension arm pin or bush excessively worn front bush (trailing arm) (5.3.4 (a) (i))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #15** 2020-01-17 17:02**MOT test number** 938719591354**Result** ✓ Passed**MOT #14** 2020-01-17 13:46**MOT test number** 623850899817**Result** ✗ Failed

- Fail** Central Rear Exhaust system insecure (6.1.2 (a))
- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Rear Exhaust silencer likely to become detached (8.1.1 (b) (ii))

MOT #13 2019-01-15 09:59**MOT test number** 987592830609**Result** ✓ Passed**MOT #12** 2019-01-15 09:58**MOT test number** 306734836363**Result** ✗ Failed

- Pass with rectification** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

MOT #11 2018-01-16 16:58**MOT test number** 497804106520**Result** ✓ Passed

- Advice** Rear exhaust bracket broken off

**MOT #10** 2018-01-15 12:04**MOT test number** 964143831528**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Offside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Rear exhaust bracket broken off**MOT #9** 2017-01-17 09:22**MOT test number** 831998046747**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-01-18 12:41**MOT test number** 406467558931**Result** ✓ Passed**MOT #7** 2015-01-16 13:00**MOT test number** 956686415044**Result** ✓ Passed**MOT #6** 2014-01-18 11:38**MOT test number** 546208214035**Result** ✓ Passed

**MOT #5** 2014-01-16 11:47**MOT test number** 889506914013**Result** ✗ Failed**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2013-03-18 12:25**MOT test number** 806857673022**Result** ✓ Passed**MOT #3** 2012-03-26 12:12**MOT test number** 809996282001**Result** ✓ Passed**MOT #2** 2011-03-08 17:59**MOT test number** 518667561023**Result** ✓ Passed**MOT #1** 2011-03-08 17:59**MOT test number** 527757561016**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
12 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 12 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | SL08XEZ |
| Plate since | 2019-09-28 |
| Current registration | SL08XEZ |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2008-03-28 |
| Last registration | 2023-12-13 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2008-03-28 | 26 mi |
| Registration #2 | 2011-03-08 | 12.849 mi |
| Registration #3 | 2012-03-26 | 17.453 mi |
| Registration #4 | 2013-03-18 | 21.325 mi |
| Registration #5 | 2014-01-16 | 24.122 mi |
| Registration #6 | 2014-01-18 | 24.123 mi |
| Registration #7 | 2015-01-16 | 31.317 mi |
| Registration #8 | 2016-01-18 | 37.816 mi |
| Registration #9 | 2017-01-17 | 44.009 mi |
| Registration #10 | 2018-01-15 | 53.652 mi |
| Registration #11 | 2018-01-16 | 53.665 mi |
| Registration #12 | 2019-01-15 | 62.607 mi |
| Registration #13 | 2019-01-16 | 62.607 mi |
| Registration #14 | 2019-01-17 | 62.607 mi |
| Registration #15 | 2019-01-18 | 62.607 mi |
| Registration #16 | 2019-01-19 | 62.607 mi |
| Registration #17 | 2019-01-20 | 62.607 mi |
| Registration #18 | 2019-01-21 | 62.607 mi |
| Registration #19 | 2019-01-22 | 62.607 mi |
| Registration #20 | 2019-01-23 | 62.607 mi |
| Registration #21 | 2019-01-24 | 62.607 mi |
| Registration #22 | 2019-01-25 | 62.607 mi |
| Registration #23 | 2019-01-26 | 62.607 mi |
| Registration #24 | 2019-01-27 | 62.607 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1755 mm |
| Height | 1665 mm |
| Length | 4565 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1410 kg |
| Max. allowed weight | 2125 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles | 2 |
| Engine number | LF 10439901 |