



A008TWU

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2025-02-03
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	26
Total items failed	19

MOT #20	2024-01-22 19:31
MOT test number	414283608505
Result	✓ Passed
Next expiry date	2025-02-03

MOT #19	2023-01-31 17:12
MOT test number	611043395723
Result	✓ Passed

MOT #18	2022-01-26 16:56
MOT test number	662560076394
Result	✓ Passed
Advice	All direction indicators slightly discoloured (4.4.3 (a))

**MOT #17** 2022-01-26 09:01**MOT test number** 666458572258**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Central Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** All direction indicators slightly discoloured (4.4.3 (a))**MOT #16** 2021-02-04 14:10**MOT test number** 828542141676**Result** ✓ Passed**MOT #15** 2020-10-05 13:13**MOT test number** 641343422250**Result** ✓ Passed**MOT #14** 2019-05-01 13:08**MOT test number** 951475961766**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**MOT #13** 2019-05-01 12:55**MOT test number** 787804506898**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**Fail** Offside Front Road wheel badly distorted (5.2.2 (c) (i))

**MOT #12**

2018-03-21 09:18

MOT test number

352612745487

Result

✓ Passed

Advice

Front Front flexible exhaust pipe has minor blow and deteriorating.

MOT #11

2018-03-14 12:09

MOT test number

245207440802

Result

✗ Failed

Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail

Emissions not tested (7.3.A.1)

Fail

Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

Fail

Exhaust has a major leak of exhaust gases rear (7.1.2)

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10

2017-03-17 13:11

MOT test number

922327793723

Result

✓ Passed

Advice

Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #9** 2017-03-13 11:14**MOT test number** 747794297673**Result** ✗ Failed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Offside Front Front suspension has excessive play in a track control arm inner bush rear bush (2.5.B.2b)**Fail** Offside Body has a sharp edge caused by damage mirror (6.1.C.1)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Nearside Front Front suspension has excessive movement at a wishbone pin or bush rear bush (2.5.A.1c)**Fail** Nearside Rear Body has a sharp edge caused by damage (6.1.C.1)**Fail** Offside Front Body has a sharp edge caused by damage bumper (6.1.C.1)**MOT #8** 2016-03-31 08:56**MOT test number** 724734302969**Result** ✓ Passed**MOT #7** 2015-01-29 15:36**MOT test number** 197729825442**Result** ✓ Passed**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #6** 2015-01-22 09:50**MOT test number** 889092625030**Result** ✗ Failed**Fail** Offside Front suspension ball joint dust cover missing (2.4.G.2)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Fail** Centre Front Exhaust system not adequately supported (7.1.1)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #5** 2014-01-27 17:34**MOT test number** 927037624059**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-02-04 15:47**MOT test number** 235505133094**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-01-25 09:26**MOT test number** 697695522074**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2 2011-02-21 09:42

MOT test number 777292651082

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Tread depth low on edge of nearside front tyre

Notice Small cut in nearside rear tyre NOT to cords/ply

MOT #1 2011-02-18 13:19

MOT test number 905859741042

Result ✗ Failed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Tread depth low on edge of nearside front tyre

Notice Offside front healight, height adjuster motor faulty

Fail Brake servo vacuum pipe split (3.6.C.1b)

Notice Small cut in nearside rear tyre NOT to cords/ply



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
3 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	3 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-31
Last registration	2024-01-22
Complete history	See info



Registration #1	2008-03-31	13 mi
Registration #2	2011-02-18	29.990 mi
Registration #3	2011-02-21	29.990 mi
Registration #4	2012-01-25	35.213 mi
Registration #5	2013-02-04	40.615 mi
Registration #6	2014-01-27	46.717 mi
Registration #7	2015-01-22	51.104 mi
Registration #8	2015-01-29	51.110 mi
Registration #9	2016-03-31	56.247 mi
Registration #10	2017-03-13	60.515 mi
Registration #11	2017-03-17	60.519 mi
Registration #12	2018-03-31	65.247 mi
Registration #13	2019-03-31	70.515 mi
Registration #14	2020-03-31	75.783 mi
Registration #15	2021-03-31	81.051 mi
Registration #16	2022-03-31	86.319 mi
Registration #17	2023-03-31	91.587 mi
Registration #18	2024-01-22	96.855 mi
Registration #19	2024-01-22	96.855 mi
Registration #20	2024-01-22	96.855 mi
Registration #21	2024-01-22	96.855 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141