



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Black
Year of manufacture	2008
Top speed	144 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-06-18
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-26
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	17
Total items failed	12

MOT #21	2023-10-25 11:16
MOT test number	809468626188
Result	✓ Passed
Next expiry date	2024-10-26

MOT #20	2022-10-27 10:19
MOT test number	658577268879
Result	✓ Passed
Advice	Full under trays fitted covering testable items

MOT #19	2021-10-07 11:14
MOT test number	517962646565
Result	✓ Passed

MOT #18	2020-10-16 13:42
MOT test number	985883048371
Result	✓ Passed

MOT #17	2020-10-14 10:25
MOT test number	580846216738
Result	✗ Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #16** 2019-04-04 15:42**MOT test number** 719449650166**Result** ✓ Passed**MOT #15** 2019-04-04 10:19**MOT test number** 987313956410**Result** ✗ Failed**MAJOR** Offside Front Outer Brake pipe excessively corroded (1.1.11 (c))**MOT #14** 2018-04-05 11:00**MOT test number** 769365129336**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #13** 2018-04-04 08:15**MOT test number** 205902273158**Result** ✗ Failed**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front tyre has cut to sidewall**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear tyre has cut to sidewall**MOT #12** 2017-03-17 15:50**MOT test number** 497704821060**Result** ✓ Passed**Advice** Front and rear antiroll bar bushes and joints have slight lift**Advice** N/s/f inner tyre wall has slight perishing

**MOT #11** 2017-03-17 10:46**MOT test number** 556750112912**Result** ✗ Failed**Fail** Suspension arm has excessive play in a ball joint n/s/f lower rear arm (2.4.G.2)**Advice** Front and rear antiroll bar bushes and joints have slight lift**Fail** Brake pipe excessively corroded front to n/s/r (3.6.B.2c)**Advice** N/s/f inner tyre wall has slight perishing**Fail** Brake pipe excessively corroded front to o/s/r (3.6.B.2c)**MOT #10** 2016-03-22 11:40**MOT test number** 278670480976**Result** ✓ Passed**MOT #9** 2016-03-21 14:05**MOT test number** 735811425475**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #8** 2015-05-21 11:11**MOT test number** 238051545177**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #7** 2014-05-30 11:33**MOT test number** 726700454117**Result** ✓ Passed

**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #6** 2014-05-30 11:33**MOT test number** 546100154145**Result** ✗ Failed

**Pass with rectification** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**MOT #5** 2013-05-31 15:27**MOT test number** 299951453429**Result** ✓ Passed**MOT #4** 2013-05-30 16:49**MOT test number** 197380353186**Result** ✗ Failed

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Headlamp not working on dipped beam (1.7.5a)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3** 2012-05-29 14:59**MOT test number** 589200652124**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2011-04-27 12:20
MOT test number	306707011120
Result	✓ Passed

MOT #1	2011-04-26 12:59
MOT test number	247926311100
Result	✗ Failed

**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
26 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	26 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-05-22
Last registration	2023-10-25
Complete history	<a href="#">See info</a>



Registration #1	2008-05-22	26 mi
Registration #2	2011-04-26	43.065 mi
Registration #3	2011-04-27	43.067 mi
Registration #4	2012-05-29	54.452 mi
Registration #5	2013-05-30	64.817 mi
Registration #6	2013-05-31	64.829 mi
Registration #7	2014-05-30	74.771 mi
Registration #8	2015-05-21	85.667 mi
Registration #9	2016-03-21	91.835 mi
Registration #10	2016-03-22	91.835 mi
Registration #11	2017-03-17	92.865 mi
Registration #12	2018-03-22	93.895 mi
Registration #13	2019-03-22	94.925 mi
Registration #14	2020-03-22	95.955 mi
Registration #15	2021-03-22	96.985 mi
Registration #16	2022-03-22	98.015 mi
Registration #17	2023-03-22	99.045 mi
Registration #18	2024-03-22	100.075 mi
Registration #19	2025-03-22	101.105 mi
Registration #20	2026-03-22	102.135 mi
Registration #21	2027-03-22	103.165 mi
Registration #22	2028-03-22	104.195 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531044174