



report date: 2024-03-29

General information

| | |
|---------------------|------------------------------|
| Make | VOLKSWAGEN |
| Model | CARAVELLE T30 SWB W/V 130TDI |
| Colour | Blue |
| Year of manufacture | 2007 |
| Top speed | 103 mph |
| 0 - 60 mph | 16.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 128 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 2.460 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 23.9 mpg |
| Consumption extra urban | 37.2 mpg |
| Consumption combined | 31.0 mpg |
| CO2 emission | 219 g/km |
| CO2 label | K |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-28 |
| Pictures | 23 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-01 |
| MOT pass rate | 78 % |
| MOT passed | 14 |
| Failed MOT tests | 4 |
| Total advice items | 24 |
| Total items failed | 2 |

| | |
|------------------|-----------------------|
| MOT #18 | 2023-10-02 15:09 |
| MOT test number | 228800650092 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-01 |
| Advice | Exhaust is corroding. |

| | |
|-----------------|----------------------|
| MOT #17 | 2022-08-23 13:31 |
| MOT test number | 434612230953 |
| Result | ✓ Passed |
| Advice | Exhaust is corroding |

| | |
|-----------------|---|
| MOT #16 | 2022-08-23 09:38 |
| MOT test number | 792014092341 |
| Result | ✗ Failed |
| DANGEROUS | Nearside Front Electrical wiring for braking components extremely deteriorated wire is broken brake pad warning lamp is illuminated on (4.11 (b) (iii)) |
| MAJOR | Nearside Front Side repeater not working (4.4.1 (a) (ii)) |
| Advice | Exhaust is corroding |

| | |
|-----------------|------------------|
| MOT #15 | 2021-08-04 14:45 |
| MOT test number | 202334348872 |
| Result | ✓ Passed |

**MOT #14** 2021-07-30 13:36**MOT test number** 766651231737**Result** ✗ Failed**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2020-08-25 08:30**MOT test number** 346139499565**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #12** 2019-08-28 14:32**MOT test number** 666239842769**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2019-08-27 17:20**MOT test number** 631559563085**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #10** 2018-07-24 14:51**MOT test number** 554684734770**Result** ✓ Passed**MOT #9** 2017-07-06 10:34**MOT test number** 299838231409**Result** ✓ Passed**MOT #8** 2016-07-01 14:08**MOT test number** 209374997301**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-07-01 13:39**MOT test number** 854052478223**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-07-10 16:11**MOT test number** 229361995457**Result** ✓ Passed**MOT #5** 2014-07-04 14:05**MOT test number** 779125684159**Result** ✓ Passed

**MOT #4** 2013-06-17 14:14**MOT test number** 545408963125**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-06-28 16:33**MOT test number** 515500782171**Result** ✓ Passed**MOT #2** 2011-06-16 13:23**MOT test number** 558407761140**Result** ✓ Passed**MOT #1** 2010-06-21 14:28**MOT test number** 322952070181**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
1 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 1 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  PY07HZX |
| Plate since | 2024-03-29 |
| Current registration |  PY07HZX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|------------|--------|
| Finance company | XXXXXXXXXX | XXXXXX |
| Date of agreement | XXXXXXXXXX | XXXXXX |
| Agreement type | XXXXXXXXXX | XXXXXX |
| Agreement term | XXXXXXXXXX | XXXXXX |
| Agreement number | XXXXXXXXXX | XXXXXX |
| Contact info | XXXXXXXXXX | XXXXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2007-06-29 |
| Last registration | 2023-10-02 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-06-29 | 17 mi |
| Registration #2 | 2010-06-21 | 28.146 mi |
| Registration #3 | 2011-06-16 | 36.063 mi |
| Registration #4 | 2012-06-28 | 43.741 mi |
| Registration #5 | 2013-06-17 | 49.740 mi |
| Registration #6 | 2014-07-04 | 61.664 mi |
| Registration #7 | 2015-07-10 | 78.344 mi |
| Registration #8 | 2016-07-01 | 90.267 mi |
| Registration #9 | 2016-07-01 | 90.267 mi |
| Registration #10 | 2017-07-06 | 101.122 mi |
| Registration #11 | 2018-06-29 | 90.267 mi |
| Registration #12 | 2019-06-29 | 90.267 mi |
| Registration #13 | 2020-06-29 | 90.267 mi |
| Registration #14 | 2021-06-29 | 90.267 mi |
| Registration #15 | 2022-06-29 | 90.267 mi |
| Registration #16 | 2023-06-29 | 90.267 mi |
| Registration #17 | 2024-06-29 | 90.267 mi |
| Registration #18 | 2025-06-29 | 90.267 mi |
| Registration #19 | 2026-06-29 | 90.267 mi |
| Registration #20 | 2027-06-29 | 90.267 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 2242 mm |
| Height | 1969 mm |
| Length | 4890 mm |
| Max. allowed weight | 3200 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 80 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 9 |
| Engine number | BNZ 050185 |