



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Black
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 1

Date	2021-01-21
Pictures	65
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-04
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	15
Total items failed	4

MOT #19	2024-03-01 15:08
MOT test number	113210572426
Result	✓ Passed
Next expiry date	2025-03-04

MOT #18	2024-02-23 13:19
MOT test number	781840167040
Result	✗ Failed
MAJOR Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))	

MOT #17	2023-02-20 11:13
MOT test number	533253306806
Result	✓ Passed

MOT #16	2022-03-02 17:04
MOT test number	782004044517
Result	✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

**MOT #15** 2022-03-02 12:24**MOT test number** 190175151606**Result** ✗ Failed**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Rear Exhaust has a major leak of exhaust gases effecting emissions back box (6.1.2 (a))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #14** 2021-03-05 13:01**MOT test number** 410038572822**Result** ✓ Passed**MOT #13** 2021-03-04 16:47**MOT test number** 244669368880**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt upper dust cover (5.3.4 (b) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt upper dust cover (5.3.4 (b) (ii))**MOT #12** 2020-10-21 14:09**MOT test number** 241362316280**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-12-04 11:36**MOT test number** 164729687343**Result** ✓ Passed



MOT #10	2018-12-22 10:02
----------------	------------------

MOT test number	685950564181
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2017-11-21 12:29
---------------	------------------

MOT test number	405682358465
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #8	2016-11-24 11:00
---------------	------------------

MOT test number	912049711666
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2015-12-22 15:00
---------------	------------------

MOT test number	424219839361
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2015-01-02 13:10
---------------	------------------

MOT test number	729452705090
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-12-19 11:38
---------------	------------------

MOT test number	177823253387
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2012-10-31 12:16
---------------	------------------

MOT test number	637775102345
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #3** 2012-10-31 10:58**MOT test number** 475555102419**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2011-11-16 14:34**MOT test number** 238450721398**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #1** 2011-11-16 14:11**MOT test number** 885190321382**Result** ✗ Failed**Fail** Nearside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)**Advice** Parking brake lever has little reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-11-21
Last registration	2024-03-01
Complete history	See info



Registration #1	2008-11-21	15 mi
Registration #2	2011-11-16	12.516 mi
Registration #3	2011-11-16	12.516 mi
Registration #4	2012-10-31	16.748 mi
Registration #5	2012-10-31	16.748 mi
Registration #6	2013-12-19	26.314 mi
Registration #7	2015-01-02	30.666 mi
Registration #8	2015-12-22	34.705 mi
Registration #9	2016-11-24	37.117 mi
Registration #10	2017-11-21	40.229 mi
Registration #11	2018-12-22	45.194 mi
Registration #12	2019-03-28	50.000 mi
Registration #13	2019-03-28	50.000 mi
Registration #14	2019-03-28	50.000 mi
Registration #15	2019-03-28	50.000 mi
Registration #16	2019-03-28	50.000 mi
Registration #17	2019-03-28	50.000 mi
Registration #18	2019-03-28	50.000 mi
Registration #19	2019-03-28	50.000 mi
Registration #20	2019-03-28	50.000 mi
Registration #21	2019-03-28	50.000 mi
Registration #22	2019-03-28	50.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BUD524379