





report date: 2024-03-28

## General information

Make	CITROEN
Model	DS3 E-HDI FLAIR ETG6
Colour	White
Year of manufacture	2015
Top speed	114 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	91 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

## Entry 1

Date 2022-02-18

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

# MOT history

MOT expiry date	2025-05-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #10		2024-04-19 12:18
MOT test	number	956334795650
Result		✓ Passed
Next expiry date 2025-05-02		
Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		

MOT #9	2024-04-19 08:06
MOT test number	640044770680
Result	<b>×</b> Failed
Minor Nearside Windscreen damaged but not adversely affecting driver's view (3	3.2 (a) (i))
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
<b>Fail</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened from car standin (1.1.14 (a) (ii))

MOT #7

MOT test number

810994374508

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

MOT test number

Result

Minor

Offside Front Windscreen wiper blade defective slightly smearing (3.4 (b) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

S60260083417

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge 205 45 17 88W (5.2.3 (e))

Advice 1 X EXHAUST BACK BOX HANGER BROKEN / COME ADRIFT (STILL SECURE)

Advice Nearside Front Tyre worn close to legal limit/worn on edge 205 45 17 88W (5.2.3 (e))

 MOT #3
 2019-05-16 08:52

 MOT test number
 258706962656

 Result
 ✓ Passed

MOT #2 2018-05-29 16:08

MOT test number 832839063527

Result ✓ Passed

MOT #1 2018-05-29 08:58

MOT test number 209866323489

**Result** X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice O/S/R TYRE PUNCTURED - MARKED YELLOW

Advice Nearside Front Tyre worn close to legal limit/worn on edge 205 45 17 88W (5.2.3 (e))

CarCheck.co.uk page 5/12



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	2 May 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

FA15BNY

report date: 2024-03-28

# For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>.

More info >

## Plate changes

about of pliates

furthe scinors

See in this check if this CITROEN had different number plates.

ALS UK

UK UK

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



FA15BNY report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-06-30
Last registration	2024-04-19
Complete history	See info



Registration #1	2015-06-30	11 mi
Registration #2	2018-05-29	40.013 mi
Registration #3	2018-05-29	40.014 mi
Registration #4	2019-05-16	49.713 mi
Registration #5	2020-06-09	58.980 mi
Registration #6	2021-05-25	65.972 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		

More info >

CarCheck.co.uk page 11/12



FA15BNY report date: 2024-03-28

# Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1946 mm
Height	1540 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1055 kg
Max. allowed weight	1605 kg

# Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBFN0073270

CarCheck.co.uk page 12/12