





## General information

Make	VOLVO
Model	V40 T2 R-DESIGN
Colour	Blue
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	120 BHP
Max. torque	220 Nm at 1.100 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D







# Internet history

Entry 2		
Date	2021-06-11	
Pictures	15	
Listing price	View report	



source: autotrader.co.uk

Entry 1	
Date	2021-05-27
Pictures	1
Listing price	View report



source: autoonline.co.uk



# MOT history

MOT expiry date	2024-06-30
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #7	2023-06-21 11:23
MOT test number	232494407113
Result	✓ Passed
Next expiry date	2024-06-30
Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre slightl (e))	y worn on inner edge (5.2.3

MOT #6		2022-06-15 13:08
MOT test	number	910483853504
Result		✓ Passed
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Nail in tyre	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2021-07-01 16:04
MOT test number	680550042813
Result	✓ Passed





MOT #4	2021-06-21 16	:15
MOT test i	number 2453913252	68
Result	🗙 Fai	led
MAJOR	Offside Front Road wheel badly distorted inner side of rim (5.2.2 (c) (i))	
Advice (e))	Offside Rear Tyre worn close to legal limit/worn on edge worn close to legal limit, 225/45/17 (5.2	.3
MAJOR	Nearside Front Road wheel badly distorted inner side of rim (5.2.2 (c) (i))	

MOT #3		2020-06-09 08:05
MOT test	number	443977137603
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #2		2020-06-08 13:54
MOT test	number	985654473928
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>MAJOR</b> (5.2.3 (d)	Nearside Rear Tyre has a cut in excess of the requirements deep enoug i))	gh to reach the ply or cords
<b>MAJOR</b> (5.2.3 (d)	Nearside Front Tyre has a cut in excess of the requirements deep enou i))	gh to reach the ply or cords
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>MAJOR</b> (5.2.3 (d)	Offside Rear Tyre has a cut in excess of the requirements deep enough i))	to reach the ply or cords
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	





409432219705

🗸 Passed

### **MOT test number**

## Result

MOT #1

Advice

COVID-19 6 MONTH EXTENSION



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 July 2024	Expires: 30 June 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	30 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





## Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	L'ANNPE
Туре	
Damage 2	AMPLE
Damaye 2	C C C C
Date	1. St
Category	AMP
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
*********	
********	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-04-29
Last registration	2023-06-21
Complete history	See info



Registration #1	2017-04-29	23 mi
Registration #2	2020-06-08	18.338 mi
Registration #3	2020-06-09	18.340 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi

More info  $\rightarrow$ 





## Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight	
Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1457 kg
Max. allowed weight	1965 kg
Additional information	
Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	2032759