



HYUNDAI



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | HYUNDAI |
| Model | IX35 CRDI PREMIUM |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 108 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 114 BHP |
| Max. torque | 260 Nm at 1.250 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 48.7 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-13 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-05 |
| MOT pass rate | 61 % |
| MOT passed | 11 |
| Failed MOT tests | 7 |
| Total advice items | 33 |
| Total items failed | 17 |

| | |
|------------------|--|
| MOT #18 | 2023-08-04 11:25 |
| MOT test number | 527016318061 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-05 |
| Advice | Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i)) |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Rear Coil spring corroded both (5.3.1 (b) (i)) |

**MOT #17**

2023-08-03 13:19

MOT test number

133179909293

Result

✗ Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Coil spring corroded both (5.3.1 (b) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #16

2022-07-20 10:26

MOT test number

527482449982

Result

✓ Passed

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge And perished (5.2.3 (e))

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))

Advice Rear Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))

MOT #15

2021-08-06 12:08

MOT test number

589941812054

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-08-05 13:30**MOT test number** 640089128769**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13** 2021-06-25 13:16**MOT test number** 985226045229**Result** ✓ Passed**MOT #12** 2020-12-30 08:57**MOT test number** 603680554504**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Pads also low and brakes look like there sticking when hot (1.1.14 (a) (ii))**Advice** Heat shield loose under fuel tank**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-12-20 15:18**MOT test number** 776884314426**Result** ✓ Passed**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10** 2019-12-19 07:46**MOT test number** 450684886003**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Side repeater not working mirror (4.4.1 (a) (ii))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #9** 2018-12-17 13:15**MOT test number** 693401102622**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-12-13 07:57**MOT test number** 956794842697**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear disc overheated**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #7** 2017-12-15 16:53**MOT test number** 833873892544**Result** ✓ Passed

**MOT #6** 2017-12-15 08:45**MOT test number** 447804674752**Result** ✗ Failed**Fail** Nearside Rear rear brake binding (3.7.B.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2016-12-29 08:46**MOT test number** 436710974984**Result** ✓ Passed**Advice** O/s/f and n/s/f tyres age related cracking to tread**MOT #4** 2016-12-19 08:15**MOT test number** 592093149035**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear rear brake excessively fluctuating (3.7.B.3)**Advice** O/s/f and n/s/f tyres age related cracking to tread**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear rear brake excessively fluctuating (3.7.B.3)**MOT #3** 2016-01-05 10:31**MOT test number** 883962149600**Result** ✓ Passed**MOT #2** 2015-01-05 15:01**MOT test number** 406245405037**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #1 | 2015-01-05 12:08 |
| MOT test number | 558705605083 |
| Result | ✗ Failed |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) |
| Fail | Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Advice | Parking brake lever has little reserve travel (3.1.6b) |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
5 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 277 |
| MOT expiry date | 5 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2012-01-01 |
| Last registration | 2023-08-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-01-01 | 24 mi |
| Registration #2 | 2015-01-05 | 26.160 mi |
| Registration #3 | 2015-01-05 | 26.162 mi |
| Registration #4 | 2016-01-05 | 32.936 mi |
| Registration #5 | 2016-12-19 | 40.887 mi |
| Registration #6 | 2016-12-29 | 41.092 mi |
| Registration #7 | 2017-12-15 | 48.155 mi |
| Registration #8 | 2017-12-15 | 48.158 mi |
| Registration #9 | 2018-12-13 | 54.949 mi |
| Registration #10 | 2018-12-17 | 55.043 mi |
| Registration #11 | 2019-01-01 | 55.043 mi |
| Registration #12 | 2019-01-01 | 55.043 mi |
| Registration #13 | 2019-01-01 | 55.043 mi |
| Registration #14 | 2019-01-01 | 55.043 mi |
| Registration #15 | 2019-01-01 | 55.043 mi |
| Registration #16 | 2019-01-01 | 55.043 mi |
| Registration #17 | 2019-01-01 | 55.043 mi |
| Registration #18 | 2019-01-01 | 55.043 mi |
| Registration #19 | 2019-01-01 | 55.043 mi |
| Registration #20 | 2019-01-01 | 55.043 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 88% |
| Pedestrian | 54% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1820 mm |
| Height | 1670 mm |
| Length | 4410 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1537 kg |
| Max. allowed weight | 1940 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

Engine number D4FDCZ075394