



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	White
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2025-04-23
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #13	2024-04-22 11:49
MOT test number	113147379004
Result	✓ Passed
Next expiry date	2025-04-23

MOT #12	2023-04-17 12:39
MOT test number	823153220952
Result	✓ Passed

MOT #11	2022-03-26 13:35
MOT test number	117966378668
Result	✓ Passed
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides front arms bushes (5.3.4 (a) (i))

**MOT #10**

2021-04-23 09:31

**MOT test number**

591801954637

**Result**

✓ Passed

**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9**

2020-04-24 10:48

**MOT test number**

699892349339

**Result**

✓ Passed

**Advice** Heavy surface corrosion to front subframe**Advice** Front wishbone rear bushes perished & unbonding slightly**Advice** Water in nsf daytime running light unit**Advice** Heavy surface corrosion to various underbody panels**Advice** Slight binding recorded on rear wheels**MOT #8**

2019-03-23 13:19

**MOT test number**

259330310653

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))**Minor** Offside Rear Tyre obviously under inflated Nail in tyre (5.2.3 (h) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material Both rear pipes slightly corroded (1.1.11 (c))

**MOT #7** 2019-03-23 12:35**MOT test number** 855688377964**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively Both front wipers smearing (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))**Advice** Rear Brake pipe corroded, covered in grease or other material Both rear pipes slightly corroded (1.1.11 (c))**Minor** Offside Rear Tyre obviously under inflated Nail in tyre (5.2.3 (h) (i))**MOT #6** 2018-03-27 10:43**MOT test number** 577790212581**Result** ✓ Passed**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2016-12-13 12:24**MOT test number** 826512550701**Result** ✓ Passed**MOT #4** 2015-06-19 16:45**MOT test number** 776880875150**Result** ✓ Passed**MOT #3** 2014-06-19 10:03**MOT test number** 158010974182**Result** ✓ Passed**MOT #2** 2013-05-28 10:44**MOT test number** 216698943477**Result** ✓ Passed



MOT #1	2012-06-19 12:35
MOT test number	309091672155
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
23 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	23 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	DE09XEL
Plate since	2019-09-28
Current registration	DE09XEL
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-05-26
Last registration	2024-04-22
Complete history	<a href="#">See info</a>



Registration #1	2009-05-26	27 mi
Registration #2	2012-06-19	19.115 mi
Registration #3	2013-05-28	21.683 mi
Registration #4	2014-06-19	33.550 mi
Registration #5	2015-06-19	44.182 mi
Registration #6	2016-12-13	59.552 mi
Registration #7	2018-03-27	64.704 mi
Registration #8	2019-05-26	75.277 mi
Registration #9	2020-05-26	85.277 mi
Registration #10	2021-05-26	95.277 mi
Registration #11	2022-05-26	105.277 mi
Registration #12	2023-05-26	115.277 mi
Registration #13	2024-05-26	125.277 mi
Registration #14	2025-05-26	135.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1KR0827053