



report date: 2024-03-28

## General information

Make	VOLVO
Model	XC90 D5 R-DESIGN AWD
Colour	Black
Year of manufacture	2014
Top speed	127 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.4 mpg
CO2 emission	215 g/km
CO2 label	K






Internet history

Entry 2

Date	2021-07-25
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	16
Total items failed	1

MOT #9	2024-01-18 15:40
MOT test number	812726450397
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Nearside Rear Passenger seat(s) missing at time of test rear rear seat not fitted
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Passenger seat(s) missing at time of test rear rear seat not fitted



MOT #8 2024-01-17 14:23

MOT test number 772947639684

Result ✗ Failed

**DANGEROUS** Nearside Front Body component likely to become detached mud flap loose (6.2.1 (a) (ii))

**Advice** Offside Rear Passenger seat(s) missing at time of test rear rear seat not fitted

**DANGEROUS** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Rear Passenger seat(s) missing at time of test rear rear seat not fitted

**DANGEROUS** Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**DANGEROUS** Offside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7 2023-01-18 17:06

MOT test number 893540947740

Result ✓ Passed

MOT #6 2021-11-25 12:07

MOT test number 470669239871

Result ✓ Passed

MOT #5 2020-09-11 08:31

MOT test number 787565316772

Result ✓ Passed

MOT #4 2019-09-04 14:23

MOT test number 642816369650

Result ✓ Passed

**MOT #3** 2019-09-04 14:23**MOT test number** 455877186841**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #2** 2018-09-03 08:55**MOT test number** 112475431163**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2017-09-06 14:10**MOT test number** 599759371438**Result** ✓ Passed**Advice** Engine cover and under tray fitted obstruct view



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
17 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	17 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-01
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2014-09-01	29 mi
Registration #2	2017-09-06	24.416 mi
Registration #3	2018-09-03	35.995 mi
Registration #4	2019-09-04	43.373 mi
Registration #5	2019-09-04	43.373 mi
Registration #6	2020-09-11	51.894 mi
Registration #7	2020-09-11	51.894 mi
Registration #8	2020-09-11	51.894 mi
Registration #9	2020-09-11	51.894 mi
Registration #10	2020-09-11	51.894 mi
Registration #11	2020-09-11	51.894 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2112 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2171 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	1413567
---------------	---------