





report date: 2024-03-29

General information

Make	JAGUAR
Model	XK8 SOVRN 4.0
Colour	Blue
Year of manufacture	1996
Top speed	144 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	245 BHP
Max. torque	392 Nm at 4.000 rpm
Engine capacity	3.980 сс
Cylinders	6
Fuel type	Petrol
Consumption city	16.7 mpg
Consumption extra urban	28.0 mpg
Consumption combined	22.2 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 2

Date 2021-10-16

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-09-14
Pictures	8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-16
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	27
Total items failed	15

MOT #25	2023-10-02 11:54
MOT test number	397712488223
Result	✓ Passed
Next expiry date	2024-10-16

MOT #24	2022-10-17 11:54
MOT test number	847696795513
Result	✓ Passed

MOT #23	2021-09-13 11:14
MOT test number	579907552687
Result	✓ Passed

MOT test number 490739436135

Result × Failed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced Outer sill panel (7.1.1 (a) (i))

Fail Offside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #21

MOT test number

S58981294160

Result

Minor

Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor

Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #20

MOT test number

360066509302

Result

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Nearside Front Fosition famp flot working (4.2.1 (a) (ii))	
MOT #19	2019-01-17 12:42
MOT test number	272213494806
Result	✓ Passed
MOT #18	2018-01-19 16:04
MOT test number	461837807187
Result	✓ Passed
MOT #17	2016-12-15 16:49
MOT test number	585071466044
Result	✓ Passed

MOT #16	2015-12-14 16:03
MOT test number	695959440102
Result	✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT test number 198566454309

MOT #14 2013-12-23 13:34

MOT test number 329237553368

Result

Passed

MOT #13 2013-01-14 12:02

MOT test number 486714613002

Result
✓ Passed

MOT #12 2012-01-13 14:59

MOT test number 156363612405

Result
✓ Passed

Advice Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt

(2.4.G.2)

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #11 2012-01-13 14:59

MOT test number 138453412401

Result X Failed

Pass with rectification Nearside Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Brake pipe slightly corroded (3.6.B.2c)

Pass with rectification Nearside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)

Advice Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2,4,G,2)

Pass with rectification Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

MOT #10 2010-07-29 12:04

MOT test number 620440110299

Result × Failed

Advice Nearside Lower Ball joint has slight play (2.2.B.1f)

Notice Suspension joint nearside lower dust cover split/missing

Pass with rectification Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

MOT #9 2010-07-29 12:04

MOT test number 190950110219

Result ✓ Passed

Advice Nearside Lower Ball joint has slight play (2.2.B.1f)

Notice Suspension joint nearside lower dust cover split/missing

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #8		2009-04-07 14:24
MOT test	number	403177899066
Result		✓ Passed
Notice	Suspension joint nearside lower dust cover split/missing	
Notice	Slight play in nearside and offside rear suspention	
Advice	Nearside Front Lower Ball joint has slight play (2.2.B.1f)	
Notice	Suspension joint offside lower dust cover split/missing	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7		2009-04-07 09:41
MOT test	number	211987099008
Result		X Failed
Advice	Nearside Front Lower Ball joint has slight play (2.2.B.1f)	
Notice	Suspension joint offside lower dust cover split/missing	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Suspension joint nearside lower dust cover split/missing	
Notice	Slight play in nearside and offside rear suspention	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		

MOT #6	2008-02-14 12:00
MOT test number	130045748455
Result	✓ Passed
MOT #5	2007-08-18 11:00
MOT test number	782570337257
Result	✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #4 2007-08-16 15:49

MOT test number 271868427216

Result X Failed

Fail Nearside Front Upper Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #3 2006-08-21 10:29

MOT test number 474043336266

Result \rightarrow Passed

MOT #2 2005-10-14 10:44

MOT test number 783287785245

MOT #1 2005-10-13 14:25

MOT test number 464736485289

Result X Failed

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Nearside Headlamp aim too low when the centre of the headlamp is below 850mm from the ground (1.6.B2)

Fail Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail Offside Headlamp aim too low when the centre of the headlamp is below 850mm from the ground (1.6.B2)

CarCheck.co.uk page 8/15



report date: 2024-03-29





Days left 186

MOT expiry date 16 October 2024

Full MOT history See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

P555WMC

report date: 2024-03-29

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR? Check it in the premium report and see all owner registrations. Download the full report here .	JAR
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY	
More info	> >

Plate changes

More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	1996-10-22
Last registration	2023-10-02
Complete history	See info



Registration #1	1996-10-22	14 mi
Registration #2	2005-10-13	38.289 mi
Registration #3	2005-10-14	38.289 mi
Registration #4	2006-08-21	42.453 mi
Registration #5	2007-08-16	45.826 mi
Registration #6	2007-08-18	45.864 mi
Registration #7	2008-02-14	47.825 mi
Registration #8	2009-04-07	49.456 mi
Registration #9	2009-04-07	49.456 mi
Registration #10	2010-07-29	49.652 mi
Registration #11	2012-01-13	49.975 mi
Registration #12	2013-01-14	51.428 mi
Registration #13	2013-12-23	53.145 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		71,777 es

CarCheck.co.uk page 14/15



report date: 2024-03-29

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	9JPFRB150880

CarCheck.co.uk page 15/15