



DE580PC

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg






Internet history

Entry 1

Date	2021-10-09
Pictures	6
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #14	2022-04-05 15:50
MOT test number	512399514919
Result	✓ Passed
Next expiry date	2023-04-19
Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sill (5.3.6 (a) (i))	
Advice Parking brake lever has little reserve travel	
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sill (5.3.6 (a) (i))	

MOT #13	2022-04-05 10:01
MOT test number	550381859709
Result	✗ Failed
Advice Parking brake lever has little reserve travel	
Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sill (5.3.6 (a) (i))	
Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sill (5.3.6 (a) (i))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #12	2021-04-20 15:43
MOT test number	488804150941
Result	✓ Passed
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Slight corrosion on suspension components	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))	

**MOT #11** 2019-07-12 09:54**MOT test number** 692872550787**Result** ✓ Passed**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))**MOT #10** 2019-07-11 10:01**MOT test number** 826421361382**Result** ✗ Failed**Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #9** 2018-07-12 12:46**MOT test number** 167038070813**Result** ✓ Passed**MOT #8** 2018-07-11 09:48**MOT test number** 100604629826**Result** ✗ Failed**Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #7** 2017-07-10 09:36**MOT test number** 182349205202**Result** ✓ Passed

**MOT #6** 2016-07-18 10:36**MOT test number** 741717295289**Result** ✓ Passed**Advice** Engine cover and under trays fitted.**MOT #5** 2015-12-10 17:07**MOT test number** 700672101747**Result** ✓ Passed**MOT #4** 2015-01-09 10:29**MOT test number** 716879005083**Result** ✓ Passed**MOT #3** 2013-11-01 10:24**MOT test number** 127405703322**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2012-10-31 14:51**MOT test number** 969795802300**Result** ✓ Passed**MOT #1** 2011-10-31 14:30**MOT test number** 525024401380**Result** ✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	DE580PC
Plate since	2019-03-29
Current registration	DE580PC
Plate since	2019-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-11-06
Last registration	2022-04-05
Complete history	See info



Registration #1	2008-11-06	26 mi
Registration #2	2011-10-31	19.247 mi
Registration #3	2012-10-31	26.783 mi
Registration #4	2013-11-01	32.022 mi
Registration #5	2015-01-09	40.919 mi
Registration #6	2015-12-10	52.355 mi
Registration #7	2016-07-18	57.175 mi
Registration #8	2017-07-10	67.272 mi
Registration #9	2018-05-29	75.377 mi
Registration #10	2019-05-29	85.377 mi
Registration #11	2020-05-29	95.377 mi
Registration #12	2021-05-29	105.377 mi
Registration #13	2022-05-29	115.377 mi
Registration #14	2023-05-29	125.377 mi
Registration #15	2024-05-29	135.377 mi
Registration #16	2025-05-29	145.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG