





report date: 2024-03-29

#### General information

Make	FORD
Model	FIESTA EDGE
Colour	Silver
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	59 BHP
Max. torque	109 Nm at 3.600 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2021-06-13

Pictures 98

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

MOT expiry date	2024-05-17
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	30
Total items failed	0

MOT #13	2023-05-09 10:25
MOT test number	586512024371
Result	✓ Passed
Next expiry date	2024-05-17
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #12		2022-05-18 08:50
MOT test	number	965817428451
Result		✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	))
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2021-05-17 14:27
MOT test number	378084554682
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #10** 2021-05-11 13:50

**MOT test number** 387257334792

Result X Failed

MAJOR Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #9 2020-08-20 16:21

MOT test number 377127459908

**Result** ✓ Passed

MOT #8 2019-08-21 11:07

**MOT test number** 340927444450

Result \rightarrow Passed

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Suspension component pin or bush slightly worn trailing (5.3.4 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Suspension component pin or bush slightly worn trailing (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

**MOT #7** 2018-09-10 14:39 **MOT** test number 231496754162 Result ✓ Passed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge also nail in (5.2.3 (e)) **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** 

**MOT #6** 2018-09-10 13:41 **MOT** test number 603220130364 Result **x** Failed **Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **MAJOR** Exhaust has a major leak of exhaust gases back box split (6.1.2 (a)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) **MAJOR** Advice Nearside Front Tyre worn close to legal limit/worn on edge also nail in (5.2.3 (e)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5	2017-09-07 13:11
MOT test number	752736823410
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4		2016-09-07 14:22
MOT test	number	857887466182
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Slight smear from wipers	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #3	2015-09-10 11:08
MOT test number	817866386218
Result	✓ Passed
MOT #2	2014-09-04 12:44
MOT test number	397037444296
Result	✓ Passed
MOT #1	2013-09-05 09:26
MOT test number	658228643217
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	17 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
HARMAN CONTRACTOR CONT	
************	
***************************************	
***************************************	
	More info >
Plate changes	
Coo in this shook if this FORD had different number plates	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK NEW
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-31
Last registration	2023-05-09
Complete history	See info



Registration #1	2010-07-31	6 mi
Registration #2	2013-09-05	19.554 mi
Registration #3	2014-09-04	23.243 mi
Registration #4	2015-09-10	27.109 mi
Registration #5	2016-09-07	31.658 mi
Registration #6	2017-09-07	38.206 mi
Registration #7	2018-09-10	45.526 mi
Registration #8	2018-09-10	45.526 mi
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11,117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1098 kg
Max. allowed weight	1490 kg

# Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

**Engine number** 

9K62960