



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Black
Year of manufacture	2010
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	35
Total items failed	11

MOT #16	2023-10-23 07:23
MOT test number	903468552459
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Rear radius arm bushes starting to split

MOT #15	2023-10-17 16:04
MOT test number	791776764192
Result	✗ Failed
Advice	Rear radius arm bushes starting to split
Fail	Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #14	2022-10-26 09:44
MOT test number	135607696559
Result	✓ Passed
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #13**

2021-09-08 11:04

MOT test number

506381772171

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Outer Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Under trays fitted
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2021-09-04 09:05

MOT test number

794431052313

Result

✗ Failed

- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Outer Seat belt slightly damaged (7.1.2 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Under trays fitted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2019-11-12 13:26

MOT test number

322453901825

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))

**MOT #10**

2019-11-12 11:53

MOT test number

635345074647

Result**✗ Failed**

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #9

2018-11-12 16:56

MOT test number

676832937148

Result**✓ Passed**

Advice Front brake discs worn

Advice Offside Rear tyre worn inner edge and perished

Advice Both front lower arm rear bush's perished

MOT #8

2017-10-31 17:10

MOT test number

963194784870

Result**✓ Passed**

Advice Offside rear tyre has a screw in it

Advice Rear tyres both slightly perished

MOT #7

2017-10-26 07:52

MOT test number

767036315497

Result**✗ Failed**

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Rear tyres both slightly perished

Advice Offside rear tyre has a screw in it

**MOT #6** 2016-10-22 09:56**MOT test number** 537548545170**Result** ✓ Passed**MOT #5** 2015-10-17 10:50**MOT test number** 958376557856**Result** ✓ Passed**MOT #4** 2014-10-23 17:00**MOT test number** 148156294259**Result** ✓ Passed**Notice** Diesel to clean for test**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2013-10-23 13:01**MOT test number** 889346193267**Result** ✓ Passed**MOT #2** 2013-03-25 16:38**MOT test number** 105404983457**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Notice** Mark on windscreen**Notice** Both rear tyres outer sidewalls damaged in poor condition**Notice** Offside rear tyre worn on inner edge



MOT #1

2013-03-25 13:40

MOT test number

716534683050

Result

✗ Failed

Fail

Nearside Rear Statutory seat belt missing (5.1.1)

Notice

Offside rear tyre worn on inner edge

Notice

Nail in nearside rear tyre

Fail

Nearside Registration plate lamp not working (1.1.C.1d)

Notice

Mark on windscreen

Fail

Offside Rear Statutory seat belt missing (5.1.1)

Notice

Both rear tyres outer sidewalls damaged in poor condition



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-29
Last registration	2023-10-23
Complete history	See info



Registration #1	2010-03-29	20 mi
Registration #2	2013-03-25	31.772 mi
Registration #3	2013-03-25	31.773 mi
Registration #4	2013-10-23	37.284 mi
Registration #5	2014-10-23	48.031 mi
Registration #6	2015-10-17	55.552 mi
Registration #7	2016-10-22	64.652 mi
Registration #8	2017-10-26	72.099 mi
Registration #9	2017-10-31	72.127 mi
Registration #10	2018-03-29	75.277 mi
Registration #11	2018-03-29	75.277 mi
Registration #12	2018-03-29	75.277 mi
Registration #13	2018-03-29	75.277 mi
Registration #14	2018-03-29	75.277 mi
Registration #15	2018-03-29	75.277 mi
Registration #16	2018-03-29	75.277 mi
Registration #17	2018-03-29	75.277 mi
Registration #18	2018-03-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C99289