



report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER TD4 GS
Colour	Black
Year of manufacture	2014
Top speed	112 mph
0 - 100 km/h	11.7 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	110 kW / 150 HP / 150 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G



Internet history

Entry 2

Date	2021-09-04
Pictures	30
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-03
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	18
Total items failed	9

MOT #11	2023-06-28 12:52
MOT test number	715199797557
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2023-06-27 10:39

MOT test number

492654832070

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #9

2022-06-30 07:21

MOT test number

311591198402

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2022-06-28 14:09**MOT test number** 867756865253**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Headlamp aim not tested (4.1.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))**MOT #7** 2021-06-25 08:15**MOT test number** 210732656567**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2021-06-25 08:15**MOT test number** 780476388526**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #5** 2020-06-26 11:00**MOT test number** 986522984124**Result** ✓ Passed**MOT #4** 2019-06-20 12:04**MOT test number** 346746245140**Result** ✓ Passed



MOT #3	2018-06-15 10:15
MOT test number	847623977247
Result	✓ Passed

MOT #2	2018-06-15 10:15
MOT test number	153940886602
Result	✗ Failed
<div>Pass with rectification</div> Offside Headlamp aim too far to the left (4.1.2 (a))	

MOT #1	2017-06-22 11:00
MOT test number	313911109583
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 January 2024

✓

MOT

Expires:
29 June 2024

Tax status	Expired at 31 January 2024
Days left	88 days too late
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	ND14GFE
Plate since	2024-03-28
Current registration	ND14GFE
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-06-28
Last registration	2023-06-28
Complete history	See info



Registration #1	2014-06-28	26 mi
Registration #2	2017-06-22	45.282 mi
Registration #3	2018-06-15	59.109 mi
Registration #4	2018-06-15	59.109 mi
Registration #5	2019-06-20	71.834 mi
Registration #6	2020-06-26	82.781 mi
Registration #7	2021-06-25	90.013 mi
Registration #8	2022-06-28	95.277 mi
Registration #9	2022-06-28	95.277 mi
Registration #10	2022-06-28	95.277 mi
Registration #11	2022-06-28	95.277 mi
Registration #12	2022-06-28	95.277 mi
Registration #13	2022-06-28	95.277 mi
Registration #14	2023-06-28	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1735 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ794075741224DT