





report date: 2024-03-29

General information

Make	MINI
Model	MINI ONE
Colour	Black
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-22

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-20
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #12	2023-05-31 14:49
MOT test number	801511613736
Result	✓ Passed
Next expiry date	2024-06-20
Advice Under side areas not fully checked due to covers fitted	

MOT #11	2022-06-21 10:21
MOT test number	371487589842
Result	✓ Passed
MOT #10	2021-03-20 15:20
MOT test number	456318318528
Result	✓ Passed

CarCheck.co.uk page 3/13



VU11KXW

report date: 2024-03-29

MOT #9 2021-03-20 09:31

MOT test number 242450380217

Result × Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2020-03-21 13:06

MOT test number 232709135286

✓ Passed

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre on 3mm (5.2.3 (e))

Advice Nearside Rear Nail in tyre

Result

Advice Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

2019-03-23 11:46 **MOT #7**

MOT test number 165961779681

Result ✓ Passed

Advice Anti-roll bar pin or bush worn but not resulting in excessive movement both rear bushes (5.3.4 (a) (i))

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number
616455687938

Result
Advice Oil leak
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front exhaust flexi broken

MOT test number

Result

Advice
Oil leak

Advice
Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

731440486302

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Rear tyres cracking

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

MOT test number

159945885048

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT test number

Fesult

Pass with rectification

Windscreen washer provides insufficient washer liquid (8.2.3)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2014-03-24 16:30

MOT test number 739423184067

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report have the current and see all owner registrations.		e?
THE STATE OF THE S		

	More info	>
Plate changes See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-28
Last registration	2023-05-31
Complete history	See info



Registration #1	2011-03-28	24 mi
Registration #2	2014-03-24	23.426 mi
Registration #3	2015-03-26	27.497 mi
Registration #4	2016-03-22	31.780 mi
Registration #5	2017-03-18	35.682 mi
Registration #6	2018-03-19	39.341 mi
Registration #7	2019-03-23	42.823 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 44
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		10.777 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles2Engine numberB560J085