



report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Silver
Year of manufacture	-
Top speed	140 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	249 Nm at 4.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	35.8 mpg
Consumption combined	27.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-01
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #19	2021-02-01 12:56
MOT test number	275526623662
Result	✓ Passed
Next expiry date	2022-02-03
Advice	Rear Outer suspension rod dust covers perished

MOT #18	2021-01-20 11:27
MOT test number	290873163980
Result	✗ Failed
Advice	Rear Outer suspension rod dust covers perished
MAJOR	Offside Headlamp aim too low (4.1.2 (a))

MOT #17	2020-01-28 14:34
MOT test number	140936613575
Result	✓ Passed
Minor	Nearside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2020-01-28 09:49
MOT test number	739703374258
Result	✗ Failed
MAJOR	Nearside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both (5.3.4 (b) (ii))
Minor	Nearside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front oil on undershield



MOT #15

2019-02-04 10:30

MOT test number

844846660123

Result		✓ Passed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Minor	Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Tested in wet conditions	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Undertrays fitted	
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge tread nearing wear marker (5.2.3 (e))	
Advice	Central Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

**MOT #14**

2018-01-16 09:38

MOT test number

668654123012

Result

✓ Passed

Advice Offside Front Inner Tyre worn close to the legal limit worn smooth, recommend replacement.
235/50/17 (4.1.E.1)

Advice Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Brake fluid level low

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside front wiper blade split

Advice Offside rear sill damaged

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #13

2017-01-03 10:27

MOT test number

551580334464

Result

✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside wiper blade split

Advice Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Inner Tyre worn close to the legal limit 235/50/17 (4.1.E.1)

Advice Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Nail in tyre

**MOT #12** 2016-01-06 10:05**MOT test number** 174403500316**Result** ✓ Passed**MOT #11** 2015-01-06 15:02**MOT test number** 686576605043**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**MOT #10** 2015-01-06 11:07**MOT test number** 206966305003**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2014-01-03 10:32**MOT test number** 546153604046**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2013-01-08 09:29**MOT test number** 717508403045**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Notice** Rear tyres worn to 3mm**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2012-01-17 11:52**MOT test number** 957727612059**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2012-01-17 09:39**MOT test number** 419767112064**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2011-01-18 09:49**MOT test number** 426518611031**Result** ✓ Passed**Notice** Wipers split**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Sill covers and undershields all fitted**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2010-01-26 09:52**MOT test number** 363436220021**Result** ✓ Passed**Notice** Wheelswap front to rear recommended to even out tyre wear**Notice** Brake pads front and rear over 70% worn**MOT #3** 2009-01-29 16:13**MOT test number** 600119529001**Result** ✓ Passed**MOT #2** 2007-07-13 08:28**MOT test number** 884564497155**Result** ✓ Passed**MOT #1** 2007-07-11 15:30**MOT test number** 134812397145**Result** ✗ Failed**Fail** Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear brake caliper leaking (3.6.A.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-05-22
Last registration	2021-02-01
Complete history	See info



Registration #1	2004-05-22	20 mi
Registration #2	2007-07-11	8.761 mi
Registration #3	2007-07-13	8.761 mi
Registration #4	2009-01-29	26.853 mi
Registration #5	2010-01-26	38.846 mi
Registration #6	2011-01-18	48.981 mi
Registration #7	2012-01-17	58.744 mi
Registration #8	2012-01-17	58.745 mi
Registration #9	2013-01-08	66.021 mi
Registration #10	2014-01-03	71.770 mi
Registration #11	2015-01-06	77.197 mi
Registration #12	2016-01-06	82.624 mi
Registration #13	2017-01-06	88.051 mi
Registration #14	2018-01-06	93.478 mi
Registration #15	2019-01-06	98.905 mi
Registration #16	2020-01-06	104.332 mi
Registration #17	2021-01-06	109.759 mi
Registration #18	2022-01-06	115.186 mi
Registration #19	2023-01-06	120.613 mi
Registration #20	2024-01-06	126.040 mi
Registration #21	2025-01-06	131.467 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1663 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	450455358JB