





### General information

| Make                | VOLVO                |
|---------------------|----------------------|
| Model               | XC60 D4 MOMENTUM AWD |
| Colour              | Grey                 |
| Year of manufacture | 2018                 |
| Top speed           | 127 mph              |
| 0 - 60 mph          | 8.3 seconds          |
| Gearbox             | 8 speed automatic    |

## Engine & fuel consumption

| Power                | 188 BHP             |
|----------------------|---------------------|
| Max. torque          | 400 Nm at 1.750 rpm |
| Engine capacity      | 1.969 cc            |
| Cylinders            | 4                   |
| Fuel type            | Diesel              |
| Consumption combined | 2.8 mpg             |
| CO2 emission         | 144 g/km            |
| CO2 label            | F                   |





# Internet history

Entry 1

Date Pictures 2022-02-14

43

Listing price

View report



source: autotrader.co.uk



## MOT history

| MOT expiry date    | 2024-11-16 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 3          |
| Total items failed | 0          |

| MOT #3   | 2023-11-10 14:52 |
|--|------------------|
| MOT test number  | 877807897137     |
| Result   | ✓ Passed         |
| Next expiry date   | 2024-11-16       |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |

| MOT #2   | 2022-11-08 10:28 |
|--|------------------|
| MOT test number  | 920076272049     |
| Result   | ✓ Passed         |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |

| MOT #1  | 2021-11-04 11:08 |
|---|------------------|
| MOT test number   | 463179341842     |
| Result  | ✓ Passed         |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |



Tax & MOT check

| √<br>Taxed                    | ✓<br>MOT                            |
|-------------------------------|-------------------------------------|
| <b>Tax due:</b><br>1 May 2024 | <b>Expires:</b><br>16 November 2024 |
| Tax status                    | Valid until 1 May                   |
| Days left                     | 2                                   |
| MOT expiry date               | 16 November 2024                    |
| Full MOT history              | See MOT history                     |

## Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | н          |
| First licence fee (12 months)                        | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |          |
|----------|----------|
| Date     | FEIDO    |
| Category | 4. ARMPE |
| Туре     |          |
| Damage 2 | AMPL     |
|          | F Stores |
| Date     | 1.E      |
| Category | ante     |
| Туре     |          |

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.00.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******   |             |
|--|-------------|
| ***********  |             |
| *******  |             |
| ******   |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLVO had different number plates. |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Correct registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

|                            | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 5               |
| First mileage registration | 2018-11-17      |
| Last registration          | 2023-11-10      |
| Complete history           | <u>See info</u> |



| Registration #1 | 2018-11-17 | 10 mi      |
|-----------------|------------|------------|
| Registration #2 | 2021-11-04 | 42.360 mi  |
| Registration #3 |            | 11.777 esi |
| Registration #4 |            | 11.777 est |
| Registration #5 |            | 11.222 esi |

More info >






## Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 50482 |                  |
| 60501 |                  |
| 60566 |                  |
| 60567 |                  |
| 60569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 98%             |
| Children       | 87%             |
| Pedestrian     | 76%             |
| Safety systems | 95%             |
| Overall rating | 90%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1999 mm          |
| Height                            | 1658 mm          |
| Length                            | 4688 mm          |
| Wheel base                        | 2865 mm          |
| Kerb weight                       | 1837 kg          |
| Max. allowed weight               | 2450 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 60 I             |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 10/10     |

| Number of axles | 2       |
|-----------------|---------|
| Engine number   | 2839783 |