



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO 2700 L1H1 CDTI P/V SPORTIVE ECOFLEX S/S
Colour	Black
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G





MOT history

MOT expiry date	2025-04-24
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	24
Total items failed	16

MOT #9	2024-04-22 13:18
MOT test number	138806900906
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Wheel trim fitted to each wheel
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8**

2024-04-18 10:41

MOT test number

571491435986

Result**✗ Failed****Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Wheel trim fitted to each wheel**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Side repeater incorrect colour (4.4.3 (a))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))



MOT #72023-04-25 14:00

MOT test number560147465305

Result

✓ Passed

- Advice

Under trays fitted
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Wheel trim fitted to each wheel
- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Under tray insecure
- Advice

Items removed from driver's view prior to test

**MOT #6**

2023-04-25 09:51

MOT test number

706614116884

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice

Items removed from driver's view prior to test

Fail

Nearside Front Side repeater incorrect colour (4.4.3 (a))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice

Under trays fitted

Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice

Wheel trim fitted to each wheel

Fail

Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Under tray insecure

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #5

2022-04-07 13:27

MOT test number

593133053307

Result**✓ Passed****Advice**

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #4

2021-04-08 10:20

MOT test number

151092869274

Result**✓ Passed**



MOT #3	2021-04-06 16:33
---------------	------------------

MOT test number	822576989006
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice	Nsf shocker damp,nsf cv boot damp
---------------	-----------------------------------

Fail	Offside Headlamp aim too high (4.1.2 (a))
-------------	-------------------------------------------

MOT #2	2020-05-27 08:07
---------------	------------------

MOT test number	851952920924
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2020-01-08 14:16
---------------	------------------

MOT test number	978666015576
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-06-29
Last registration	2024-04-22
Complete history	See info



Registration #1	2016-06-29	27 mi
Registration #2	2020-01-08	41.794 mi
Registration #3	2020-05-27	41.921 mi
Registration #4	2021-04-06	62.042 mi
Registration #5	2021-04-08	62.042 mi
Registration #6	2022-05-29	62.042 mi
Registration #7	2022-05-29	62.042 mi
Registration #8	2022-05-29	62.042 mi
Registration #9	2022-05-29	62.042 mi
Registration #10	2024-04-22	62.042 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1970 mm
Length	4998 mm
Kerb weight	1683 kg
Max. allowed weight	2760 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MB - C118686LWU