





## General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC CDTI ECOFLEX S/S
Colour	Red
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С







# Internet history

Entry 4	
Date	2021-11-26
Pictures	0
Listing price	View report

#### source: heycar.co.uk

### Entry 3

Date	2021-10-21
Pictures	29
Listing price	View report



source: yesauto.com

Entry 2	
Date	2021-10-08
Pictures	0
Listing price	View report
source: cargurus.co.uk	

Entry 1	
Date	2021-10-08
Pictures	0
Listing price	View report

source: heycar.co.uk



## MOT history

MOT expiry date	2024-12-14
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	21
Total items failed	0

MOT #11	2023-12-07 08:51
MOT test number	804152988139
Result	✓ Passed
Next expiry date	2024-12-14

MOT #10		2022-12-01 15:53
MOT test	number	448233157890
Result		Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))	

MOT #9	2022-12-01 12:59
MOT test number	738984038642
Result	× Failed
<b>DANGEROUS</b> Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Power steering pipe/hose has slight seepage (2.1.5 (a))	
Advice Offside Rear Nail in tyre	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	





MOT #8	2021-12-15 15:15
MOT test number	752526189586
Result	✓ Passed
MOT #7	2021-10-08 09:18
MOT test number	638190011289
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6		2021-08-31 09:19
MOT test	number	266746326248
Result		✓ Passed
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.	3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5		2020-09-15 09:23
MOT test	number	461321070165
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Nail in tyre	





МОТ #4		2019-09-24 06:42
MOT test	number	242444205403
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Items removed from driver's view prior to test	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2018-10-22 14:36
MOT test number	433530691765
Result	✓ Passed
MOT #2	2018-10-15 15:39
MOT test number	861132256675

Result

**DANGEROUS** Nearside Front Seat belt webbing significantly weakened webbing cut (7.1.2 (b) (ii))

MOT #1	2017-10-30 14:33
MOT test number	146117172585
Result	✓ Passed

🗙 Failed



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	<b>MOT</b> Expires: 14 December 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	14 December 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
ACCOUNTS AND A DESCRIPTION OF A DESCRIPR	
And and a second s	
**********	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-12-17
Last registration	2023-12-07
Complete history	<u>See info</u>



Registration #1	2014-12-17	22 mi
Registration #2	2017-10-30	7.692 mi
Registration #3	2018-10-15	16.252 mi
Registration #4	2018-10-22	16.306 mi
Registration #5	2019-09-24	22.599 mi
Registration #6	2020-09-15	28.036 mi
Registration #7	2021-08-31	35.501 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.277 est

More info >





# Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2040 kg
Additional information	
Additional information Fuel delivery	Direct Injection
	Direct Injection 5
Fuel delivery	-
Fuel delivery Number of doors	5
Fuel delivery Number of doors Number of seats	5 5