



report date: 2024-03-29

General information

Make	CITROEN
Model	DS4 E-HDI AIRDREAM DSTYLE
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-01-18
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	29
Total items failed	6

MOT #12	2024-01-12 10:28
MOT test number	852423813954
Result	✓ Passed
Next expiry date	2025-01-23

MOT #11	2023-01-19 10:44
MOT test number	347516119159
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2023-01-19 09:55

MOT test number

692921318311

Result

✗ Failed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))**MOT #9**

2022-01-24 17:04

MOT test number

992391357150

Result

✓ Passed

MOT #8

2021-02-04 16:38

MOT test number

721505673271

Result

✓ Passed

MOT #7

2020-02-15 10:41

MOT test number

281535138802

Result

✓ Passed

Advice Tyre worn close to legal limit/worn on edge both rear and n.s.f worn inner edge and o.s.f bald inner edge. n.s.f 3.5 mm, o.s.f 3.2 mm, n.s.r, 4 mm and o.s.r 3.7 mm. (5.2.3 (e))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**MOT #6** 2020-02-15 10:41**MOT test number** 102794545542**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Tyre worn close to legal limit/worn on edge both rear and n.s.f worn inner edge and o.s.f bald inner edge. n.s.f 3.5 mm, o.s.f 3.2 mm, n.s.r, 4 mm and o.s.r 3.7 mm. (5.2.3 (e))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))**MOT #5** 2019-02-23 12:54**MOT test number** 713929278330**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4** 2019-02-23 08:43**MOT test number** 609100462644**Result** ✗ Failed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Outer Tyre has a lump, caused by separation or partial failure of its structure 225/45z18 (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-02-17 10:56**MOT test number** 710261737172**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 1.71 mm (4.1.E.1)**Advice** 225/45R18 EXTRA LOAD

**MOT #2**

2018-02-17 09:09

MOT test number

598880790767

Result**✗ Failed****Fail**

Offside Front Tyre tread depth below requirements of 1.6mm 1.57 mm (4.1.E.1)

Advice

225/45R18 EXTRA LOAD

Fail

Nearside Front Tyre has a tear, caused by separation or partial failure of its structure INNER WALL SPLIT (4.1.D.1b)

Advice

Offside Rear Tyre worn close to the legal limit 1.71 mm (4.1.E.1)

Advice

225/45R18 EXTRA LOAD

MOT #1

2017-02-24 13:43

MOT test number

454021471189

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-01
Last registration	2024-01-12
Complete history	See info



Registration #1	2014-03-01	17 mi
Registration #2	2017-02-24	31.641 mi
Registration #3	2018-02-17	49.645 mi
Registration #4	2018-02-17	49.645 mi
Registration #5	2019-02-23	65.853 mi
Registration #6	2019-02-23	65.835 mi
Registration #7	2020-02-15	80.356 mi
Registration #8	2020-02-22	95.277 mi
Registration #9	2020-02-22	95.277 mi
Registration #10	2020-02-22	95.277 mi
Registration #11	2020-02-22	95.277 mi
Registration #12	2020-02-22	95.277 mi
Registration #13	2020-02-22	95.277 mi
Registration #14	2020-02-22	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFV0033073