





report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC TDCI
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-08

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2024-12-20
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	34
Total items failed	5

MOT #16		2023-11-22 10:00
MOT test	number	589273366733
Result		✓ Passed
Next expiry date 2024-12-		2024-12-20
Advice Nearside Rear Tyre slightly damaged/cracking or perishing 195/60/15 (5.2.3 (d) (ii))		
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #15	2022-11-29 16:41
MOT test number	939511473967
Result	✓ Passed
Advice N/s/f tyre 1.6mm 195/60/15h	

MOT #14		2021-12-21 05:55
MOT test number		133218994934
Result		✓ Passed
MOT #13		2021-12-21 05:55
MOT test number		988424381993
Result		× Failed
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #12

MOT test number

2021-01-28 10:34

MOT test number

202964500107

Result

Advice Rear axle corroded

MOT #11 2021-01-26 13:25 **MOT** test number 831556299857 Result **X** Failed **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Nearside Rear All direction indicators incorrect colour (4.4.3 (a)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Rear axle corroded Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Fail Offside Rear All direction indicators incorrect colour (4.4.3 (a))

MOT #10

MOT test number

117660798131

Result

Advice Oil leak from engine area

MOT test number

Front number plate cracked


Advice Coolant leak

Advice Nearside Rear coil spring has slight corrosion

CarCheck.co.uk page 4/14



report date: 2024-03-29



MOT #7		2018-03-22 15:53
MOT test	number	156914788333
Result		✓ Passed
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Offside Front coil spring corroded (2.4.C.1b)	

MOT #6		2017-03-06 10:16
MOT test	number	427965582468
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Rear exhaust silencer corroded.	
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #5	2016-03-17 09:41
MOT test number	294458578473
Result	✓ Passed
Advice Child seat fitted, unable to fully check main belt	
Advice Rear exhaust box in poor condition	

MOT #4		2014-11-24 10:00
MOT test	number	226818924323
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Unable to properly check outer sills due to plastic trims	
Notice	Rear exhaust box has slight corrosion on outer cover	
Notice	Offside front tyre has slight wear on inside + outside edges	

MOT #3		2013-12-05 10:09
MOT test	number	119729333381
Result		✓ Passed
Advice	Coil spring corroded (2.4.C.1b)	
Notice	Both rear tyres cracking around tyre tread	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2012-12-21 15:23
MOT test number	437876752333
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1 2012-05-28 15:39

MOT test number 389339942123

Result ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check





Expires: 20 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

CP09GGF

report date: 2024-03-29

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes

More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-12
Last registration	2023-11-22
Complete history	See info



Registration #1	2009-06-12	21 mi
Registration #2	2012-05-28	9.433 mi
Registration #3	2012-12-21	11.190 mi
Registration #4	2013-12-05	17.638 mi
Registration #5	2014-11-24	24.875 mi
Registration #6	2016-03-17	34.967 mi
Registration #7	2017-03-06	42.156 mi
Registration #8	2018-03-22	46.758 mi
Registration #9	2019-03-21	50.772 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 14/1