



report date: 2024-03-29

General information

Make	AUDI
Model	A1 TDI SPORT
Colour	Silver
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





MOT history

MOT expiry date	2024-03-31
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	31
Total items failed	9

MOT #142024-04-09 14:42

MOT test number654075826012

ResultX Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Nail in tyre and tyre out of shape
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Headlamp aim unable to be tested (4.1.2 (b))

MOT #132023-03-28 16:56

MOT test number350288672797

Result✓ Passed



MOT #12	2023-03-27 16:01
MOT test number	493852565087
Result	✗ Failed
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #11	2022-04-01 14:00
MOT test number	792504884885
Result	✓ Passed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bush (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #10	2021-03-17 16:42
MOT test number	382696670711
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9	2021-03-17 16:42
MOT test number	717884637539
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2020-03-09 15:13
MOT test number	279012209747
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #7** 2019-03-08 11:25**MOT test number** 788660102020**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2019-03-08 11:25**MOT test number** 418057969348**Result** ✗ Failed

- Advice** Offside Front Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))
- Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2018-02-07 13:46**MOT test number** 521795146853**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2017-02-20 15:29**MOT test number** 157315821872**Result** ✓ Passed**Advice** Slight cut offside front tyre inner sidewall**MOT #3** 2016-02-13 09:56**MOT test number** 482122215490**Result** ✓ Passed**Advice** Engine covers and under trays fitted**MOT #2** 2015-01-31 10:10**MOT test number** 709891235042**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2015-01-30 15:56**MOT test number** 215410235072**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✗
MOT

Expired:
31 March 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	31 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-02-24
Last registration	2024-04-09
Complete history	See info



Registration #1	2012-02-24	21 mi
Registration #2	2015-01-30	32.878 mi
Registration #3	2015-01-31	32.878 mi
Registration #4	2016-02-13	45.815 mi
Registration #5	2017-02-20	53.393 mi
Registration #6	2018-02-07	62.705 mi
Registration #7	2019-03-08	70.293 mi
Registration #8	2019-03-08	70.293 mi
Registration #9	2019-03-08	70.293 mi
Registration #10	2019-03-08	70.293 mi
Registration #11	2019-03-08	70.293 mi
Registration #12	2019-03-08	70.293 mi
Registration #13	2019-03-08	70.293 mi
Registration #14	2019-03-08	70.293 mi
Registration #15	2019-03-08	70.293 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1740 mm
Height	1416 mm
Length	3954 mm
Wheel base	2469 mm
Kerb weight	1140 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2

Engine number

CAYA43387