




report date: 2024-03-29

## General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Grey
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-27
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-06-23
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	16
Total items failed	6

**MOT #15** 2023-06-15 12:24**MOT test number** 821154383470**Result** ✓ Passed**Next expiry date** 2024-06-23**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #14** 2023-06-15 11:57**MOT test number** 527890022595**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Headlamp light source and lamp not compatible (4.1.4 (c))**Fail** Nearside Front Headlamp light source and lamp not compatible (4.1.4 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2022-06-24 14:43**MOT test number** 328046809604**Result** ✓ Passed

**MOT #12** 2021-05-13 10:12**MOT test number** 498301747243**Result** ✓ Passed**MOT #11** 2021-05-13 10:12**MOT test number** 215686856791**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #10** 2020-06-05 13:15**MOT test number** 458359707213**Result** ✓ Passed**MOT #9** 2020-06-05 10:25**MOT test number** 414154799327**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #8** 2019-04-03 14:53**MOT test number** 114477124658**Result** ✓ Passed**MOT #7** 2018-04-11 08:04**MOT test number** 191754946105**Result** ✓ Passed

**MOT #6** 2017-04-21 13:56**MOT test number** 889674789400**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-04-12 09:12**MOT test number** 975010508180**Result** ✓ Passed**Advice** Offside Rear tyre perished**Advice** Nearside Rear tyre perished**MOT #4** 2015-04-14 14:41**MOT test number** 347734705145**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-04-03 09:56**MOT test number** 856513394097**Result** ✓ Passed**MOT #2** 2013-03-26 09:20**MOT test number** 138585583055**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #12012-04-27 11:26

MOT test number488028612195

Result

✓ Passed

NoticeEngine covers fitted obscuring some components in the engine bay

NoticeFront brake pads low

NoticeUnder-trays fitted obscuring some underside components

NoticeItems removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
23 June 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	23 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-04-29
Last registration	2023-06-15
Complete history	<a href="#">See info</a>



Registration #1	2009-04-29	11 mi
Registration #2	2012-04-27	37.650 mi
Registration #3	2013-03-26	51.622 mi
Registration #4	2014-04-03	66.191 mi
Registration #5	2015-04-14	79.381 mi
Registration #6	2016-04-12	91.408 mi
Registration #7	2017-04-21	98.432 mi
Registration #8	2018-04-11	124.892 mi
Registration #9	2019-04-03	151.592 mi
Registration #10	2020-04-03	151.592 mi
Registration #11	2020-04-03	151.592 mi
Registration #12	2020-04-03	151.592 mi
Registration #13	2020-04-03	151.592 mi
Registration #14	2020-04-03	151.592 mi
Registration #15	2020-04-03	151.592 mi
Registration #16	2020-04-03	151.592 mi
Registration #17	2020-04-03	151.592 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2142 mm
Height	1713 mm
Length	4628 mm
Wheel base	2774 mm
Kerb weight	1890 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	701175