



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT GTE ADVANCE DSG
Colour	Black
Year of manufacture	2018
Top speed	140 mph
0 - 100 km/h	7.6 seconds
0 - 60 mph	7.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	115 kW / 157 HP / 215 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.395 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	166.2 mpg
CO2 emission	40 g/km
CO2 label	A





Internet history

Entry 2

Date	2022-06-03
Pictures	5
Listing price	View report



source: yesauto.com

Entry 1

Date	2022-05-13
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-22
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #6	2024-03-08 15:00
MOT test number	992429561553
Result	✓ Passed
Next expiry date	2025-03-22
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces (1.1.14 (a) (ii))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5	2023-03-23 12:21
MOT test number	933826119653
Result	✓ Passed
Advice	Nearside Front Has a cut not in excess of requirements deep enough to reach ply or cords
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	N/s/f and n/s/r wheel inner rims slightly dented
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2023-03-17 14:59**MOT test number** 167652667057**Result** ✗ Failed**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #3** 2023-03-10 14:01**MOT test number** 148029233992**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2022-03-11 14:07**MOT test number** 275191973844**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inside edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inside edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #1** 2021-02-15 17:00**MOT test number** 420139082300**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
22 March 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XX18XUE
Plate since	2019-03-28
Current registration	XX18XUE
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-14
Last registration	2024-03-08
Complete history	See info



Registration #1	2018-03-14	24 mi
Registration #2	2021-02-15	25.416 mi
Registration #3	2022-03-11	32.076 mi
Registration #4	2023-03-08	32.076 mi
Registration #5	2023-03-08	32.076 mi
Registration #6	2023-03-08	32.076 mi
Registration #7	2023-03-08	32.076 mi
Registration #8	2023-03-08	32.076 mi
Registration #9	2023-03-08	32.076 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1660 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CUKC118668