





report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	221 g/km
CO2 label	K



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2021-09-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-17
Pictures	35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-09
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	15
Total items failed	6

MOT #16	2023-07-06 12:57
MOT test number	772212945636
Result	✓ Passed
Next expiry date	2024-07-09
Advice I)MIL lamp lit ii)exhaust middle hangers corroded and fractured and minor gas leakage on pipe iii)slight fluctuation in near side rear brake reading	

MOT #15	2022-07-09 08:44
MOT test number	334156289825
Result	✓ Passed
Advice Front Registration plate deteriorated but not l	ikely to be misread (0.1 (b))

MOT #14	2022-07-08 09:59
MOT test number	242637260329
Result	× Failed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Offside Brake pipe excessively corroded front to rear (1.1.11 (c))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))	

CarCheck.co.uk page 3/13



DG57YXU

report date: 2024-03-28

MOT #13 2021-06-25 14:18

MOT test number 945188143568

Result ✓ Passed

Advice Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #12 2021-06-25 08:04

MOT test number 862015799977

Result X Failed

Advice Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Fail Offside Front Inner Suspension component pin or bush excessively worn (5.3.4 (a) (i))

Advice Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-06-29 15:59

MOT test number 127558092580

Minor Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #10 2020-06-29 07:58

MOT test number 841496523668

Result X Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Minor Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

CarCheck.co.uk page 4/13



DG57YXU

report date: 2024-03-28

MOT #9		2019-07-02 07:56
MOT test	number	847433020199
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Exhaust Y piece fractured.	

MOT #8	2018-07-10 09:58
MOT test number	837706700783
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge needs replacing	g (5.2.3 (e))

MOT #7	2017-07-08 10:38
MOT test number	853131599488
Result	✓ Passed
MOT #6	2016-12-01 12:09
MOT test number	938182181562
Result	✓ Passed
MOT #5	2015-05-29 07:27
MOT test number	408099945183
Result	✓ Passed
MOT #4	2014-02-18 08:04
MOT test number	387519244012
Result	✓ Passed
MOT #3	2012-09-24 15:53
MOT test number	869428862263
Result	✓ Passed

CarCheck.co.uk page 5/13



DG57YXU

report date: 2024-03-28

MOT #2	2011-08-08 08:32
MOT test number	899470921221
Result	✓ Passed
MOT #1	2010-08-31 11:27
MOT test number	720263740250
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date	
Category	
Туре	
Damage 2	

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history		
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.		ort

	More info	>
Plate changes		
See in this check if this MERCEDES had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-28
Last registration	2023-07-06
Complete history	See info



Registration #1	2007-09-28	12 mi
Registration #2	2010-08-31	13.664 mi
Registration #3	2011-08-08	19.054 mi
Registration #4	2012-09-24	25.962 mi
Registration #5	2014-02-18	28.659 mi
Registration #6	2015-05-29	29.042 mi
Registration #7	2016-12-01	29.505 mi
Registration #8	2017-07-08	30.347 mi
Registration #9	2018-07-10	37.387 mi
Registration #10	2019-07-02	42.588 mi
Registration #11		11.777 es
Registration #12		11.117 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430836652

CarCheck.co.uk page 13/13