





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 GO SE
Colour	White
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



YP18YWL

report date: 2024-03-29


Internet history

Entry 2

Date 2021-07-27


Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

 Date
 2021-07-26

 Pictures
 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-30
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #6	2023-08-24 11:04
MOT test number	190491256106
Result	✓ Passed
Next expiry date	2024-08-30
Advice Offside Front Tyre worn clo	ose to legal limit/worn on edge (5.2.3 (e))
Advice Nearside Rear Shock absor	rbers has light misting of oil (5.3.2 (b))
Advice Nearside Front Tyre worn o	close to legal limit/worn on edge (5.2.3 (e))

MOT #5		2022-08-30 14:18
MOT test	number	748216376059
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/11



MOT #4 2022-08-30 14:18

MOT test number 734681998755

Result X Failed

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3 2021-08-31 15:48

MOT test number 850906110321

MOT #2 2021-05-24 10:40

MOT test number 297089849426

Result ✓ Passed

MOT #1 2021-05-24 10:05

MOT test number 384911624264

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-
Premium rate (12 months)	£ 570,00,-


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

Plate changes	More info >
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SILE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-31
Last registration	2023-08-24
Complete history	See info



Registration #1	2018-05-31	16 mi
Registration #2	2021-05-24	60.201 mi
Registration #3	2021-05-24	60.201 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



YP18YWL

report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number G4LAJM823965