



PEUGEOT



BP06PKK


report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Blue
Year of manufacture	2006
Top speed	129 mph
0 - 60 mph	10.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	192 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-08-28
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-29
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	43
Total items failed	8

MOT #22	2023-12-30 11:37
MOT test number	442243727816
Result	✓ Passed
Next expiry date	2024-12-29
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Slight play in near side steering arm
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2023-12-29 16:21
MOT test number	136364148145
Result	✗ Failed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2022-12-30 13:02

MOT test number

418882594179

Result

✓ Passed

Advice Front brake disks heavily corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Slight play in near side steering arm**Advice** Oil leak**MOT #19**

2022-12-30 13:02

MOT test number

816907101117

Result

✗ Failed

Pass with rectification Front Position lamp not working both (4.2.1 (a) (ii))**Advice** Front brake disks heavily corroded**Advice** Slight play in near side steering arm**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Oil leak**MOT #18**

2021-12-02 11:33

MOT test number

427051797745

Result

✓ Passed

Advice Front Play in steering rack inner joint(s) both**Advice** Front Integral body structure is repaired but structural rigidity is not significantly reduced rear under sealed. (6.1.1 (d) (i))**MOT #17**

2020-03-06 15:29

MOT test number

448161020981

Result

✓ Passed

**MOT #16**

2020-03-06 09:54

MOT test number

348601791021

Result**✗ Failed**

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Headlamp aim too low both (4.1.2 (a))
- MAJOR** Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))

MOT #15

2019-03-02 11:34

MOT test number

902161710382

Result**✓ Passed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2019-02-28 10:18**MOT test number** 604520921975**Result** ✗ Failed**DANGEROUS** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2018-02-20 10:53**MOT test number** 958492630710**Result** ✓ Passed**Advice** Front discs pitted inside**MOT #12** 2017-07-18 14:32**MOT test number** 830988558879**Result** ✓ Passed**MOT #11** 2016-07-25 09:51**MOT test number** 969915289866**Result** ✓ Passed**MOT #10** 2016-07-25 09:51**MOT test number** 168610181075**Result** ✗ Failed**Pass with rectification** Nearside Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #9** 2015-08-04 13:31**MOT test number** 187646515218**Result** ✓ Passed**MOT #8** 2015-08-04 10:06**MOT test number** 645106815213**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #7** 2014-08-05 16:02**MOT test number** 206577714287**Result** ✓ Passed**Notice** Both rear tyres cracking**MOT #6** 2014-08-05 12:11**MOT test number** 395867914295**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Both rear tyres cracking**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-07-31 14:25**MOT test number** 727172713201**Result** ✓ Passed**Notice** All tyres cracking



MOT #4	2012-08-04 12:21
MOT test number	657417812210
Result	✓ Passed
MOT #3	2011-08-06 11:20
MOT test number	869898711201
Result	✓ Passed
MOT #2	2010-08-07 10:29
MOT test number	342729510463
Result	✓ Passed
MOT #1	2009-08-01 10:36
MOT test number	270813419285
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
29 December 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	29 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-08-10
Last registration	2023-12-30
Complete history	See info



Registration #1	2006-08-10	21 mi
Registration #2	2009-08-01	17.017 mi
Registration #3	2010-08-07	20.695 mi
Registration #4	2011-08-06	24.472 mi
Registration #5	2012-08-04	27.726 mi
Registration #6	2013-07-31	31.340 mi
Registration #7	2014-08-05	36.803 mi
Registration #8	2014-08-05	36.803 mi
Registration #9	2015-08-04	42.819 mi
Registration #10	2015-08-04	42.819 mi
Registration #11	2016-07-25	47.831 mi
Registration #12	2016-07-25	47.831 mi
Registration #13	2016-07-25	47.831 mi
Registration #14	2016-07-25	47.831 mi
Registration #15	2016-07-25	47.831 mi
Registration #16	2016-07-25	47.831 mi
Registration #17	2016-07-25	47.831 mi
Registration #18	2016-07-25	47.831 mi
Registration #19	2016-07-25	47.831 mi
Registration #20	2016-07-25	47.831 mi
Registration #21	2016-07-25	47.831 mi
Registration #22	2016-07-25	47.831 mi
Registration #23	2016-07-25	47.831 mi
Registration #24	2016-07-25	47.831 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1543 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LH4P1445371